

Sheffield District - Public Register of Notices Served – April 2017 to March 2019

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	7 th April 2017
Name of Organisation:	Sheffield Gauge Plate Ltd, Bastock Road, Sheffield S6 2AE
Premises Type:	Factory (R)
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) - A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 12 (4) (a) - Arrangements for the safe handling and/or storage and/or transport of dangerous substances and/or waste containing dangerous substances is inadequate.</p> <p>Article 13 (1) (a) & 13 (2) - The fire warning system is inadequate.</p> <p>Article 14 (1) - The escape routes were obstructed.</p> <p>Article 14 (2) (b) - The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 14 (2) (f) - Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Article 14 (2) (h) - The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 17 (1) - The manual fire fighting equipment is inadequately maintained.</p> <p>Article 21 (2) (a) - Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/520
Date of compliance of notice:	

Date on which notice served:	13 th April 2017
Name of Organisation:	CeX, 27-29 High Street, Sheffield S1 2GA
Premises Type:	Shop (N)
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) - The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 14 (1) - The escape routes were obstructed.</p> <p>Article 14 (2) (b) - The escape routes and exits could not be used as quickly and as safely as possible.</p>

	<p>Article 14 (2) (g) - The escape routes were not provided with adequate signage.</p> <p>Article 17 (1) - The structural and passive fire precautions are inadequately maintained.</p> <p>Article 17 (1) - The fire alarm system is inadequately maintained.</p> <p>Article 21 (2) (a) - Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/521
Date of compliance of notice:	