

Sheffield District - Public Register of Notices Served – April 2011 to March 2013

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	21/03/2013
Name of Organisation:	Priory Lodge Hotel, 40 Wostenholm Road, Sheffield, S7 1LJ
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The fire warning and detection system are inadequate.
Reference No	EN/W/300
Date of compliance of notice:	20/05/2013

Date on which notice served:	19/03/2013
Name of Organisation:	Remar UK, 156 Matilda Street, Sheffield, S1 4QG
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out.
Reference No	EN/W/302
Date of compliance of notice:	25/04/2013

Date on which notice served:	13/03/2013
Name of Organisation:	The Forum, 59 Sandstone Road, Sheffield, S9 1AF
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. The escape routes were obstructed. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/301
Date of compliance of notice:	26/04/2013

Date on which notice served:	13/03/2013
Name of Organisation:	TH Michaels (Construction) Ltd, 87 Forncett Street, Sheffield, S4 7QG
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Safety training to employees is not repeated periodically.
Reference No	EN/W/299
Date of compliance of notice:	09/05/2013

Date on which notice served:	13/03/2013
Name of Organisation:	Sabai Rooms, 268-270 Sheffield Road, Tinsley, Sheffield, S9 1RD
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document has not been prepared.</p> <p>The fire detection system is inadequate.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The escape routes were not adequately maintained.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/298
Date of compliance of notice:	17/07/2013

Date on which notice served:	07/03/2013
Name of Organisation:	Top Edge Retail and Warehouse Unit, 95-97 Green Lane, Ecclesfield, Sheffield S35 9WY
Type of notice served:	Enforcement
Details:	<p>A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>A fire safety policy document was not available at the time of the visit.</p> <p>The fire fighting equipment is inadequate.</p> <p>The fire fighting equipment is not easily accessible.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>The structural and passive fire precautions are inadequately maintained.</p>
Reference No	EN/W/297
Date of compliance of notice:	09/09/2013

Date on which notice served:	04/03/2013
Name of Organisation:	Top Edge Warehouse Unit, 95-97 Green Lane, Ecclesfield, Sheffield, S35 9WY
Type of notice served:	Enforcement
Details:	<p>A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>A fire safety policy document was not available at the time of the visit.</p> <p>The escape routes were obstructed.</p> <p>The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p>
Reference No	EN/W/295
Date of compliance of notice:	09/09/2013

Date on which notice served:	01/03/2013
Name of Organisation:	Sabai Rooms, 268-270 Sheffield Road, Tinsley, Sheffield, S9 1RD
Type of notice served:	Prohibition
Details:	Absence of a means of giving warning in case in fire on the 2 nd floor. Absence of emergency lighting from the 2 nd floor to the ground floor.
Reference No	PN/W/296
Date of compliance of notice:	22/07/2013

Date on which notice served:	21/02/2013
Name of Organisation:	Steelhouse, 53-59 West Street, Sheffield, S1 4EQ
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. The Fire Safety Risk Assessment was not suitable and sufficient. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. A fire safety policy document has not been prepared. The risks from a dangerous substance have not been eliminated and/or reduced and/or replaced so far as is reasonably practicable. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN/W/294
Date of compliance of notice:	19/04/2013

Date on which notice served:	15/02/2013
Name of Organisation:	Wardeys, 274 Glossop Road, Sheffield, S10 2HS
Type of notice served:	Prohibition
Details:	Involves or will involve, a risk to persons on the premises in the event of fire so serious that use of the premises ought to be prohibited. The Fire and Rescue Authority are further of the opinion that the matter(s) which will give rise to the said risk are: The means of escape from the first floor, second floor and attic areas pass through the open plan kitchen on the ground floor which is a high fire risk. Persons occupying these floors would be unable to make a safe escape.
Reference No	PN/W/293
Date of compliance of notice:	15/02/2013

Date on which notice served:	06/02/2013
Name of Organisation:	Select and Save, 486-488 Glossop Road, Sheffield, S10 2Qa
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. A fire safety policy document has not been prepared. The escape routes were obstructed.

	The fire alarm system is inadequately maintained.
Reference No	EN/W/289
Date of compliance of notice:	11/03/2013

Date on which notice served:	28/01/2013
Name of Organisation:	The Glen Nursing Home, 224 Abbeydale Road South, Sheffield, S17 3LA
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequate. The escape routes and exits could not be used as quickly and as safely as possible. The structural fire precautions are inadequately maintained.
Reference No	EN/W/287
Date of compliance of notice:	19/04/2013

Date on which notice served:	20/12/2012
Name of Organisation:	Parklands Guest House, 113 Rustlings Road, Sheffield S11 7AB
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The escape routes were not adequately lit. The structural fire precautions are inadequately maintained.
Reference No	EN/W/285
Date of compliance of notice:	07/02/2013

Date on which notice served:	07/12/2012
Name of Organisation:	Parson Cross Hotel, Deerlands Avenue, Sheffield S5 8AA
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN/W/284
Date of compliance of notice:	09/01/2013

Date on which notice served:	28/11/2012
Name of Organisation:	Daisychain Daycare, 95 Langsett Road South, Oughtibridge, Sheffield S35 0GY
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes did not lead, as directly as possible, to a place of safety. The emergency lighting is inadequately maintained.
Reference No	EN/W/282
Date of compliance of notice:	15/03/2013

Date on which notice served:	27/11/2012
Name of Organisation:	Emin Supermarket, 74-78 Spital Hill, Sheffield, S4 7LG
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The escape routes were obstructed. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not provided with adequate signage. The structural fire precautions are inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/281
Date of compliance of notice:	25/01/2013

Date on which notice served:	19/11/2012
Name of Organisation:	Prestige Services (Yorkshire) Limited, 7 High House Terrace, Sheffield S6 2HX
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The escape routes were not adequately lit. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/277
Date of compliance of notice:	08/02/2013

Date on which notice served:	16/10/2012
Name of Organisation:	The Bed Factory, Unit 3, 164-170 Queens Road, Sheffield S2 4DU
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The fire fighting equipment is inadequate. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not provided with adequate signage. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN/W/274
Date of compliance of notice:	18/12/2012

Date on which notice served:	10/09/2012
Name of Organisation:	New Bridge Inn, 4 Penistone Road North, Sheffield S6 1LQ
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequate. The fire fighting equipment is inadequate.

	Emergency doors do not open in the direction of escape. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/269
Date of compliance of notice:	08/11/2012

Date on which notice served:	20/08/2012
Name of Organisation:	Firth Rixon Forgings Ltd (Factory), River Don Site, Brightside Lane, Sheffield S9 1RZ
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The fire safety policy document was not suitable and sufficient. The fire warning system is inadequate. The escape routes were not provided with adequate signage. The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits. The emergency lighting is inadequately maintained Safety training to employees is not repeated periodically.
Reference No	EN/W/267
Date of compliance of notice:	05/06/2013

Date on which notice served:	16/08/2012
Name of Organisation:	Firth Rixon Forgings Ltd (Maintenance Workshop), River Don Site, Brightside Lane, Sheffield S9 1RZ
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes were obstructed. The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits. Safety training to employees is not repeated periodically.
Reference No	EN/W/267
Date of compliance of notice:	05/06/2013

Date on which notice served:	16/08/2012
Name of Organisation:	Butlers Express, 190 Brook Hill, Sheffield S3 7HE
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained.
Reference No	EN/W/266
Date of compliance of notice:	11/09/2012

Date on which notice served:	16/08/2012
Name of Organisation:	Lookers Ford, Kia Alfa, 10 Savile Street East, Sheffield S4 7UQ
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees.

	<p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The fire safety policy document was not suitable and sufficient.</p> <p>The measures to control the risks and/or mitigate the detrimental effects of fire from a dangerous substance is not in accordance with the measures specified in Part 4 of the Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>Insufficient competent persons have been nominated to carry out evacuation procedures.</p> <p>Inadequate information is made available to the emergency services to enable them to prepare a response procedure and/or precautionary plan in the event of an accident, incident or emergency involving dangerous substances.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/264
Date of compliance of notice:	28/09/2012

Date on which notice served:	07/08/2012
Name of Organisation:	Toyota Pentagon, 260 Penistone Road, Sheffield S6 2FG
Type of notice served:	Enforcement
Details:	<p>A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/260
Date of compliance of notice:	27/09/2012

Date on which notice served:	18/07/2012
Name of Organisation:	Daisycourt Properties Ltd (In Administration), Block C, 15 Riverdale Road, Sheffield S10 3FG
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p>
Reference No	EN/W/251
Date of compliance of notice:	13/03/2014

Date on which notice served:	16/07/2012
Name of Organisation:	Daisycourt Properties Ltd (In Administration), Block B, 15 Riverdale Road, Sheffield S10 3FG
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p>
Reference No	EN/W/250
Date of compliance of notice:	24th November 2014

Date on which notice served:	12/07/12
Name of Organisation:	154 Arundel Street, Sheffield S1 4RE
Type of notice served:	Prohibition
Details:	Inadequate means of giving warning in case of fire to the 2 nd floor. The 2 nd floor of the premises should not be used.
Reference No	PN/W/253
Date of compliance of notice:	06/12/2012

Date on which notice served:	29/06/2012
Name of Organisation:	Biggins Brothers, 154 Arundel Street, Sheffield S1 4RE
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of the Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>A fire safety policy document has not been prepared.</p> <p>The risks from a dangerous substance have not been eliminated and/or reduced and/or replaced so far as is reasonably practicable.</p> <p>The fire warning system is inadequate.</p> <p>The escape routes were obstructed.</p> <p>The escape routes did not lead, as directly as possible, to a place of safety.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The escape routes were not provided with adequate signage.</p> <p>The escape routes were not adequately lit.</p> <p>Inadequate information is available on emergency arrangements to safeguard persons from dangerous substances involved in an accident, incident or emergency.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained – Ground Floor Workshop.</p> <p>Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.</p> <p>Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.</p> <p>Failure to inform other responsible persons sharing the same premises of the risks arising out of, or in connection with, your undertaking.</p>
Reference No	WN/W/248
Date of compliance of notice:	03/12/2012

Date on which notice served:	20/06/2012
Name of Organisation:	154 Arundel Street, Sheffield, S12 4RE
Type of notice served:	Prohibition
Details:	Inadequate means of giving warning in case of fire to the 1 st and 2 nd floors. The 1 st and 2 nd floors of the premises should not be used.

Reference No	PN/W/245
Date of compliance of notice:	12/07/12

Date on which notice served:	15/06/2012
Name of Organisation:	Pandora's Massage Suite, 387 Attercliffe Road, Sheffield S9 3QU
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>A fire safety policy document was not available at the time of the visit.</p> <p>The fire detection system is inadequate.</p> <p>The escape routes were obstructed.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/243
Date of compliance of notice:	15/08/2012

Date on which notice served:	15/06/2012
Name of Organisation:	Park Gardeners Club, Cricket Inn Road, Sheffield S2 5AT
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>The Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document has not been prepared.</p> <p>Insufficient competent persons have been nominated to implement fire fighting measures.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The escape routes were not adequately lit.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/242
Date of compliance of notice:	10/08/2012

Date on which notice served:	28/05/2012
Name of Organisation:	The Forty Foot, 11 Donovan Road, Sheffield S5 8TA

Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The passive fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/240
Date of compliance of notice:	02/08/2012

Date on which notice served:	23/05/2012
Name of Organisation:	Darwin House, Darwin Lane, Sheffield S10 3FE
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. Preventative and protection measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. The escape routes and exits could not be used as quickly and as safely as possible. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/239
Date of compliance of notice:	10/09/2012

Date on which notice served:	22/05/2012
Name of Organisation:	84 Sidney Street, Sheffield S3 8LB
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN/W/237
Date of compliance of notice:	25/07/2012

Date on which notice served:	17/05/2012
Name of Organisation:	Tap and Barrel, 42 Waingate, Sheffield S3 8LB
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient.

	<p>The fire detection system is inadequate.</p> <p>The fire warning system is inadequate.</p> <p>The fire fighting equipment is inadequate.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/236
Date of compliance of notice:	02/08/2012

Date on which notice served:	11/05/2012
Name of Organisation:	Norfolk Arms, 26 Dixon Lane, Sheffield S1 2AL
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The fire detection system is inadequate.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Inadequate safety training is provided to employees on their being exposed to a new or increased risk.</p>
Reference No	EN/W/232
Date of compliance of notice:	27/07/2012

Date on which notice served:	09/05/2012
Name of Organisation:	The White House, Manchester Road, Hollow Meadows, Sheffield S6 6GH
Type of notice served:	Enforcement
Details:	<p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The fire detection system is inadequate.</p> <p>All bedroom fire doors should meet the requirements of a 30 minute fire door and be fitted with self closing devices unless otherwise demonstrated in your risk assessment to an equivalent level of safety.</p> <p>If a self closing door is required to be in the open position then consideration should be given to the installation of automatic door hold open/release devices.</p>
Reference No	EN/W/231
Date of compliance of notice:	06/08/2012

Date on which notice served:	09/05/2012
Name of Organisation:	The Corner Pin, 231-233 Carlisle Street East, Sheffield S4 7QN
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm and emergency lighting system are inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p>

	Safety training to employees is not repeated periodically.
Reference No	EN/W/230
Date of compliance of notice:	15/08/2012

Date on which notice served:	27/04/2012
Name of Organisation:	2-4 Bank Street, Sheffield S1 2DS and 39-41 Snig Hill, Sheffield S3 8NA
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. The fire detection and warning system are inadequate. The escape routes and exits could not be used as quickly and as safely as possible. The fire alarm system is inadequately maintained. Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005. Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN/W/224
Date of compliance of notice:	28/05/2012

Date on which notice served:	25/04/2012
Name of Organisation:	(re: Daisycourt Properties Limited in Administration), Block B, 15 Riverdale Road, Sheffield S10 3FA
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible.
Reference No	EN/W/222
Date of compliance of notice:	24th November 2014

Date on which notice served:	25/04/2012
Name of Organisation:	Enforcement
Type of notice served:	(re: Daisycourt Properties Limited in Administration), Block C, 15 Riverdale Road, Sheffield S10 3FA
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible.
Reference No	EN/W/221
Date of compliance of notice:	13/03/2014

Date on which notice served:	17/04/2012
Name of Organisation:	Darwins Alloy Castings Ltd, Fitzwilliam Works, Sheffield Road, Sheffield, S9 1RL
Type of notice served:	Enforcement

Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment has not been reviewed as a result of a recent fire. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN/W/217
Date of compliance of notice:	12/10/2012

Date on which notice served:	12/04/2012
Name of Organisation:	POW UK Ltd, 121 Matilda Street, Sheffield, S1 4QG
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequate. The escape routes and exits could not be used as quickly and as safely as possible. The passive fire precautions are inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN/W/219
Date of compliance of notice:	19/09/2012

Date on which notice served:	27/03/2012
Name of Organisation:	Block A, Woodview Court, Walkley Lane, Sheffield, S6 2NX
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. The escape routes and exits could not be used as quickly and as safely as possible. The structural fire precautions are inadequately maintained.
Reference No	EN/W/214
Date of compliance of notice:	05/12/2012

Date on which notice served:	27/03/2012
Name of Organisation:	Block B, Woodview Court, Walkley Lane, Sheffield, S6 2NX
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. The escape routes and exits could not be used as quickly and as safely as possible. The structural fire precautions are inadequately maintained.
Reference No	EN/W/213
Date of compliance of notice:	20/12/2012

Date on which notice served:	22/03/2012
Name of Organisation:	Riverside Apartments, 2 Northbank, The Wicker, Sheffield, S3 8JT
Type of notice served:	Enforcement

Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. The Fire Safety Risk Assessment was not suitable and sufficient. The structural fire precautions are inadequately maintained. The automatic fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/211
Date of compliance of notice:	31/05/2012

Date on which notice served:	15/03/2012
Name of Organisation:	Woodview Care Home, 2 Richmond Park Way, Sheffield, S13 8HU
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/207
Date of compliance of notice:	06/06/2012

Date on which notice served:	16/02/12
Name of Organisation:	Endeavour Training, Grimesthorpe Junior School, Grimesthorpe, Sheffield, S4 8FB
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The passive fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/202
Date of compliance of notice:	17/05/2012

Date on which notice served:	13/02/2012
Name of Organisation:	The Railway Inn, Bramall Lane, Sheffield S2 4FR
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. The fire warning system is inadequate. The structural fire precautions are inadequately maintained.
Reference No	EN/W/201
Date of compliance of notice:	04/05/2012

Date on which notice served:	10/02/2012
Name of Organisation:	Hydra Tots and Hydra Kids Private Day Nursery, Nether Lane, Ecclesfield, Sheffield S35 9ZX
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out.
Reference No	EN/W/200

Date of compliance of notice:	13/03/2012
-------------------------------	-------------------

Date on which notice served:	02/02/2012
Name of Organisation:	S1 Art Space, 120 Trafalgar Street, Sheffield, S1 3JT
Type of notice served:	Enforcement
Details:	<p>The matters identified during the fire safety audit carried out on 19th January 2012 indicate that the existing fire risk assessment does not appear to be 'suitable and sufficient'. The fire risk assessment should therefore be reviewed and re-addressed.</p> <p>A fire safety policy document has not been prepared.</p> <p>The fire detection system is inadequate.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>The passive fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/198
Date of compliance of notice:	06/09/2012

Date on which notice served:	26/01/2012
Name of Organisation:	S1 Art Space, 120 Trafalgar Street, Sheffield S1 4JT
Type of notice served:	Prohibition
Details:	Unsatisfactory means of escape from the section of the Mezzanine Level containing Studios 6, 7, 8 and 9
Reference No	PN/W/195
Date of compliance of notice:	15/10/2012

Date on which notice served:	20/01/2012
Name of Organisation:	S1 Art Space, 120 Trafalgar Street, Sheffield S1 4JT
Type of notice served:	Prohibition
Details:	Unsatisfactory means of escape from the mezzanine level via the front staircase.
Reference No	PN/W/193
Date of compliance of notice:	26/01/2012

Date on which notice served:	20/01/2012
Name of Organisation:	Corton Sheet Metal Fabrication Limited, 1 Parkway Avenue, Sheffield S9 4WA
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The fire safety policy document was not suitable and sufficient.</p> <p>Insufficient competent persons have been nominated to implement fire fighting measures.</p> <p>The escape routes were not provided with adequate signage.</p>

	Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/192
Date of compliance of notice:	11/04/2012

Date on which notice served:	18/01/2012
Name of Organisation:	147 Hotshots, 596a Attercliffe Road, Sheffield S9 3QS
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>A Fire Safety Risk Assessment has to been carried out.</p> <p>The escape routes were obstructed.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The passive fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.</p> <p>Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.</p>
Reference No	W/EN/189
Date of compliance of notice:	16/02/2012

Date on which notice served:	17/01/2012
Name of Organisation:	Universal Components UK Limited, 8 Stevenson Way, Attercliffe, Sheffield S9 3WZ
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes were obstructed.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The number, distribution and/or size of escape routes and exits is inadequate.</p> <p>The escape routes were not provided with adequate signage.</p> <p>The passive fire precautions are inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/188
Date of compliance of notice:	05/04/2012

Date on which notice served:	11/01/2012
Name of Organisation:	Riverside Court, 4-10 Nursery Street, Sheffield S3 8GG
Type of notice served:	Enforcement

Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire Safety Risk Assessment has not been carried out. The escape routes were obstructed. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/186
Date of compliance of notice:	23/02/2012

Date on which notice served:	04/01/2012
Name of Organisation:	Coumes Spring Childrens Centre, Naylor Road, Oughtibridge, Sheffield, S350HG
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible. The escape routes were not adequately lit. The emergency lighting is inadequately maintained. The manual fire fighting equipment is inadequately maintained. Safety training to employees is not repeated periodically.
Reference No	En/W/183
Date of compliance of notice:	07/03/2012

Date on which notice served:	30/12/2011
Name of Organisation:	Kurdistan Restaurant, 34-36 Spital Hill, Sheffield, S4 7LG
Type of notice served:	Prohibition
Details:	Unsatisfactory means of escape from first floor level. The electrical fittings are in a dangerous condition creating a potential fire hazard. Inadequate fire fighting equipment. The general fire precautions are inadequately maintained exposing relevant persons to an unacceptable level of risk.
Reference No	PN/W/185
Date of compliance of notice:	16/04/2011

Date on which notice served:	23/12/2011
Name of Organisation:	Workshop, Testing and Warehouse, Special Steel Group, Bacon Lane, Sheffield S9 3NH
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The fire warning system is inadequate. The number, distribution and/or size of escape routes and exits is inadequate. The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.
Reference No	EN/W/184
Date of compliance of notice:	23/04/2012

Date on which notice served:	23/12/2011
Name of Organisation:	The Ring Shop, Castmaster Rolls Company, 90 Stevenson Road, Sheffield S9 3XG
Type of notice served:	Enforcement
Details:	<p>The Fire Safety Risk Assessment has not taken into account a significant change.</p> <p>The fire warning system is inadequate.</p> <p>The external fire exit (extension) is not suitable and sufficient. This requires risk assessing and suitable building work carried out in order for its safe use by anyone in an emergency.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/182
Date of compliance of notice:	02/04/2012

Date on which notice served:	23/12/2011
Name of Organisation:	Rose Cottage Nursing Home, Station Road, Halfway, Sheffield S20 3GU
Type of notice served:	Enforcement
Details:	<p>The fire detection system is inadequate.</p> <p>All bedroom doors should be constructed to 30 minutes fire resisting standard and fitted with intumescent smoke strip/seal.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>There was no evidence of an annual test to the emergency lighting system during the audit. Confirmation will be required that it has been tested in accordance with BS 5266 – 1: 2011.</p>
Reference No	EN/W/181
Date of compliance of notice:	03/05/2012

Date on which notice served:	23/12/2012
Name of Organisation:	Woodhouse Methodist Church, Chapel Street, Sheffield S13 7JL
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>The fire warning system is inadequate.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The escape routes were not provided with adequate signage.</p> <p>To provide comprehensible and relevant information to employees on risks identified by the risk assessment.</p> <p>To provide comprehensible and relevant information to employees on preventative and protective measures.</p>
Reference No	EN/W/180
Date of compliance of notice:	10/05/2012

Date on which notice served:	20/12/2011
Name of Organisation:	Heage Road Vehicle Services, Shepcote Lane, Sheffield, S9 1TX
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees.

	<p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The Fire Safety Risk Assessment has not been reviewed on a regular basis.</p> <p>A fire safety policy document was not available at the time of the visit.</p> <p>Arrangements for the safe handling and/or storage and/or transport of dangerous substances and/or waste containing dangerous substances is inadequate.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Inadequate information is displayed at the premises to enable the emergency services to undertake an appropriate response in the event of an accident, incident or emergency involving dangerous substances.</p>
Reference No	EN/W/177
Date of compliance of notice:	28/02/2012

Date on which notice served:	19/12/2011
Name of Organisation:	Victory Assembly, 99 John Street, Sheffield S2 4QX
Type of notice served:	Enforcement
Details:	A fire risk assessment has not been carried out
Reference No	EN/W/176
Date of compliance of notice:	02/02/2012

Date on which notice served:	12/12/2011
Name of Organisation:	North Hill Residential Home, 2 North Hill Road, Sheffield S5 8DS
Type of notice served:	Enforcement
Details:	<p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes and exits could not be used as quickly and as safely as possibly.</p>
Reference No	EN/W/173
Date of compliance of notice:	29/02/2012

Date on which notice served:	06/12/2011
Name of Organisation:	White Rose Court, 40-42 Clifton Avenue, Sheffield S9 4BA
Type of notice served:	Enforcement
Details:	<p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p>
Reference No	EN/W/172
Date of compliance of notice:	01/03/2012

Date on which notice served:	02/11/2011
Name of Organisation:	The Hollteck Co Ltd, 63 Jenkin Road, Sheffield, S9 1AT
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees.

	<p>A Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document has not been prepared.</p> <p>The risks from a dangerous substance have not been eliminated and/or reduced and/or replaced so far as is reasonably practicable.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Inadequate information is available on emergency arrangements to safeguard persons from dangerous substances involved in an accident, incident or emergency.</p> <p>The passive fire precautions are inadequately maintained.</p> <p>Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.</p>
Reference No	EN/W/169
Date of compliance of notice:	09/02/2012

Date on which notice served:	25/10/2011
Name of Organisation:	Bay Horse Inn, 463 Pitsmoor Road, Sheffield, S3 9AT
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>A Fire Safety Risk assessment has not been carried out.</p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>The fire warning system is inadequate.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/168
Date of compliance of notice:	12/06/2012

Date on which notice served:	21/10/2011
Name of Organisation:	Manor Castle Inn, 239 Manor Lane, Sheffield, S2 1UJ
Type of notice served:	Enforcement
Details:	<p>A Fire Safety Risk Assessment has not been carried out.</p> <p>The fire detection system is inadequate.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/W/165
Date of compliance of notice:	13/12/2011

Date on which notice served:	11/10/2011
Name of Organisation:	Former Stanley Tools, Rutland Road, Sheffield, S3 9PS
Type of notice served:	Enforcement
Details:	<p>Provision of sleeping accommodation for 20 people as advertised on Web Site constitutes a change of use and will require Building Regulations permission. This must cease immediately.</p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) order 2005.</p> <p>Failure to inform other responsible persons sharing the same premises of the risks arising out of, r in connection with, your undertaking.</p>
Reference No	EN/W/162
Date of compliance of notice:	03/12/2012

Date on which notice served:	06/10/2011
Name of Organisation:	Alpine Lodge Nursing Home,
Type of notice served:	Enforcement
Details:	<p>All bedrooms should be constructed to a 30 minutes fire resisting standard and all bedroom doors should meet the requirements of a 30 minute fire door and fitted with self-closing devices, unless otherwise demonstrated by your Fire Risk Assessment.</p> <p>If a self closing fire door is required to be in the open position then consideration should be given to automatic door hold-open/release devices for self closing fire doors. It is recommended that before fitting such devices approval is obtained from this department.</p>
Reference No	EN/W/161
Date of compliance of notice:	13/12/2011

Date on which notice served:	03/10/2011
Name of Organisation:	Cash Generator, 23-25 Haymarket, Sheffield, S1 2AW
Type of notice served:	Enforcement
Details:	<p>The Fire Safety Risk Assessment was not suitable or sufficient.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p>
Reference No	EN/W/153
Date of compliance of notice:	30/11/2011

Date on which notice served:	28/09/2011
Name of Organisation:	Beechy Knoll House, 378 Richmond Road, Sheffield, S13 8LZ
Type of notice served:	Enforcement
Details:	<p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/W/159
Date of compliance of notice:	22/12/2011

Date on which notice served:	28/09/2011
Name of Organisation:	The Pheasant Inn, 30 Trafalgar Road, Sheffield, S6 1JY
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not available at the time of the inspection. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN/W/158
Date of compliance of notice:	08/02/2012

Date on which notice served:	28/09/2011
Name of Organisation:	School Road Dental Surgery, 257 School Road, Sheffield, S10 1GQ
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes were not adequately lit. The structural fire precautions are inadequately maintained.
Reference No	EN/W/157
Date of compliance of notice:	22/11/2011

Date on which notice served:	27/09/2011
Name of Organisation:	Fulwood Sports Club, Chorley Road, Sheffield, S10 3RL
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The fire warning system is inadequate. The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits. The structural fire precautions are inadequately maintained. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/160
Date of compliance of notice:	19/04/2012

Date on which notice served:	26/09/2011
Name of Organisation:	Strines Inn, Bradfield Dale, Bradfield, Sheffield, S6 6JE
Type of notice served:	Enforcement
Details:	The fire detection system is inadequate. The fire warning system is inadequate. The escape routes were not adequately lit.
Reference No	EN/W/156
Date of compliance of notice:	02/02/2012

Date on which notice served:	22/09/2011
Name of Organisation:	Richmond Heights Nursing Home, 42b Woodhouse Road, Sheffield, S12 2AZ
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. The structural fire precautions are inadequately maintained. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/155
Date of compliance of notice:	20/01/2012

Date on which notice served:	20/09/2011
Name of Organisation:	Southern Cross Healthcare Ltd, Moorend Place Care Centre, 34 Commonsides, Sheffield, S10 1GE
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. The structural fire precautions are inadequately maintained.
Reference No	EN/W/154
Date of compliance of notice:	22/11/2011

Date on which notice served:	16/09/2011
Name of Organisation:	Traffic Systems Co-operative Ltd, 1 Roman Ridge Road, Sheffield, S9 1GB
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequate. The escape routes were not provided with adequate signage. The escape routes were not adequately lit. The escape routes and exits could not be used as quickly and as safely as possible. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Safety training to employees is not repeated periodically.
Reference No	EN/W/152
Date of compliance of notice:	15/12/2011

Date on which notice served:	13/09/2011
Name of Organisation:	GD Machinery, Unit 2 Industrial Centre, Garter Street, Sheffield, S4 7QX
Type of notice served:	Enforcement

Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document has not been prepared.</p> <p>The measures to control the risks and/or mitigate the detrimental effects of fire from a dangerous substance is not in accordance with the measures specified in Part 4 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>The fire warning system is inadequate.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The escape routes were not adequately lit.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/150
Date of compliance of notice:	05/08/2013

Date on which notice served:	12/09/2011
Name of Organisation:	Seven Hills Nursing Home, 17 Cherry Tree Road, Sheffield, S11 9AA
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The escape routes were not provided with adequate signage.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/W/149
Date of compliance of notice:	19/12/2011

Date on which notice served:	12/09/2011
Name of Organisation:	Lime Tree Residential Care Home, Devon Street/Barnsley Road, Sheffield, S4 7AJ
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>A fire safety policy document has not been prepared.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>

Reference No	EN/W/148
Date of compliance of notice:	13/02/2012

Date on which notice served:	05/09/2011
Name of Organisation:	Wainwright Crescent Respite Unit, 48 Wainwright Crescent, Sheffield, S13 8EN
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/147
Date of compliance of notice:	04/11/2011

Date on which notice served:	05/09/2011
Name of Organisation:	Balmoral Care Home, 6 Beighton Road, Sheffield S13 7PR
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. The structural fire precautions are inadequately maintained. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/146
Date of compliance of notice:	22/02/2012

Date on which notice served:	31/08/2011
Name of Organisation:	The White Rails, Burlington Street, Sheffield, S6 3DY
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. The emergency lighting is inadequately maintained.
Reference No	EN/W/143
Date of compliance of notice:	17/01/2012

Date on which notice served:	30/08/2011
Name of Organisation:	Darnall Horticultural and Floral, 647 Staniforth Road, Sheffield, S9 4RD
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/142
Date of compliance of notice:	15/12/2011

Date on which notice served:	25/08/2011
Name of Organisation:	Newfield View, 6-8 Gleadless Road, Sheffield, S12 2QH
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. A fire safety policy document has not been prepared. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/W/141
Date of compliance of notice:	28/09/2011

Date on which notice served:	13/07/2011
Name of Organisation:	KFC, Unit 1 Loundside, Burncross Road, Chapeltown, Sheffield, S35 1SF
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. The escape routes and exits could not be used as quickly and as safely as possible. The manual fire fighting equipment is inadequately maintained.
Reference No	EN/W/136
Date of compliance of notice:	06/09/2011

Date on which notice served:	22/06/2011
Name of Organisation:	Kurdistan Restaurant, 34-36 Spital Hill, Sheffield, S4 7LG
Type of notice served:	Enforcement
Details:	A Fire Risk Assessment has not been carried out. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. A fire warning system is inadequate. The escape routes and exits could not be used as quickly and as safely as possible. The structural fire precautions are inadequately maintained. The emergency lighting is inadequately maintained. To provide comprehensible and relevant information to employees on preventive and protective measures. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN/W/133
Date of compliance of notice:	28/10/2011

Date on which notice served:	05/05/2011
Name of Organisation:	Job Lot Trading Company Limited, 939 Barnsley Road, Sheffield, S5 0QJ
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of

	<p>employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>A fire safety policy document has not been prepared.</p> <p>The fire fighting equipment is not easily accessible.</p> <p>The escape routes were obstructed.</p> <p>The number, distribution and/or size of escape routes and exits is inadequate.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The escape routes were not provided with adequate signage.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/131
Date of compliance of notice:	26/07/2011

Date on which notice served:	26/04/2011
Name of Organisation:	Wicker Works, 11-15 Brunswick Road, Sheffield S3 9LW
Type of notice served:	Prohibition
Details:	<p>Inadequate means of escape in case of fire.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The number, distribution and/or size of escape routes and exits appear to be inadequate.</p> <p>A Fire Safety Risk Assessment was not available.</p> <p>Officers of this Authority must be afforded the opportunity to conduct a full inspection of these premises.</p>
Reference No	PN/W/129
Date of compliance of notice:	9th December 2014

Date on which notice served:	07/04/2011
Name of Organisation:	The Furniture Clearance Warehouse, 329 Coleford Road, Darnall, Sheffield S9 5PE
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes were obstructed.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm and emergency lighting systems are inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/W/127
Date of compliance of notice:	20/06/2011

Date on which notice served:	04/04/2011
Name of Organisation:	Cameo Stress Therapy, 228 Gleadless Road, Sheffield S2 3AF
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document has not been prepared.</p> <p>The fire detection system is inadequate.</p> <p>The fire warning system is inadequate.</p> <p>The escape routes did not lead, as directly as possible, to a place of safety.</p> <p>The escape routes were not adequately lit.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/W/125
Date of compliance of notice:	04/11/2011