

Sheffield District - Public Register of Notices Served – April 2009 to March 2011

Date on which notice served:	23/03/2011
Name of Organisation:	The Forty Foot, Donovan Road, Sheffield S5 8TA
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and those who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The Fire Safety Risk Assessment has not been reviewed on a regular basis.</p> <p>The fire detection system is inadequate.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The escape routes were not provided with adequate signage.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm system and emergency lighting system are inadequately maintained.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Safety training to employees is not repeated periodically.</p> <p>Safety training to employees is not provided in a manner appropriate to the risks identified by the risk assessment.</p>
Reference No	EN/W/123
Date of compliance of notice:	<b>09/05/2011</b>

Date on which notice served:	23/03/2011
Name of Organisation:	Cameo Stress Therapy, 228 Gleadless Road, Sheffield, S2 3AF
Type of notice served:	Prohibition/Restriction
Details:	<p>Unsatisfactory means of escape from the cellar in conjunction with a number of hazards including restricted access and egress, no means of detection or emergency lighting and inadequate fire resistance.</p>
Reference No	PN/W/124
Date of compliance of notice:	

Date on which notice served:	16/03/2011
Name of Organisation:	Ivy Park Court, 35 Ivy Park Road, Sheffield S10 3LA
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p>
Reference No	EN/W/122
Date of compliance of notice:	<b>19/09/2012</b>

Date on which notice served:	14/03/2011
Name of Organisation:	Natural Bed Company, Unit 5A Clarence Works, Effingham Road, Sheffield S4 7YS
Type of notice served:	Enforcement
Details:	<p>A Fire Safety Risk Assessment has not been carried out.</p> <p>The fire warning system is inadequate.</p>

	The emergency lighting is inadequately maintained. To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger. Inadequate safety training is provided to employees at the time when they are first employed.
Reference No	EN/W/121
Date of compliance of notice:	<b>04/07/2011</b>

Date on which notice served:	02/03/2011
Name of Organisation:	Residential Accommodation, 178 Myrtle Road, Sheffield, S2 3HJ
Type of notice served:	Prohibition
Details:	The storage in any container or vehicle of petroleum spirit within the domestic premises.
Reference No	PN/W/119
Date of compliance of notice:	<b>02/03/2011</b>

Date on which notice served:	18/02/2011
Name of Organisation:	East House Public House, 18 Spital Hill, Sheffield, S4 7LG
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained.
Reference No	EN/W/118
Date of compliance of notice:	<b>30/03/2011</b>

Date on which notice served:	22/10/2010
Name of Organisation:	Green Room, 150-154 Devonshire Street, Sheffield, S3 7SG
Type of notice served:	Enforcement
Details:	A fire risk assessment has not been reviewed. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed.
Reference No	EN/W/109
Date of compliance of notice:	<b>11/02/2011</b>

Date on which notice served:	01/10/2010
Name of Organisation:	Stocksbridge Neuro Rehabilitation Centre, 2a Haywood Lane, Deepcar, Sheffield S36 2QE
Type of notice served:	Enforcement
Details:	The fire risk assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and safely as possible.
Reference No	EN/W/108
Date of compliance of notice:	<b>02/02/2011</b>

Date on which notice served:	01/10/2010
Name of Organisation:	Stocksbridge Neuro Rehabilitation Centre, 2a Haywood Lane,

	Deepcar, Sheffield, S36 2QE
Type of notice served:	Enforcement
Details:	The fire risk assessment was not suitable and sufficient. The structural fire precautions are inadequately maintained.
Reference No	EN/W/107
Date of compliance of notice:	<b>19/11/2010</b>

Date on which notice served:	29/09/2010
Name of Organisation:	Warehouse Management Ltd, Terminal and Grain Warehouse, Victoria Quays, Wharf Street, Sheffield, S2 5SY
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment has not been reviewed on a regular basis. The fire detection system is inadequate. The fire warning system is inadequate. The fire fighting equipment is not easily accessible. The structural fire precautions are inadequately maintained.
Reference No	EN/W/106
Date of compliance of notice:	<b>11/02/2011</b>

Date on which notice served:	23/09/2010
Name of Organisation:	MTM Machining UK Limited, Dore House Industrial Estate, 4 Orgreave Crescent, Sheffield S13 9NQ
Type of notice served:	Enforcement
Details:	The escape routes were obstructed. The structural fire precautions are inadequately maintained.
Reference No	EN/W/105
Date of compliance of notice:	<b>01/11/2010</b>

Date on which notice served:	16/09/2010
Name of Organisation:	Campbell Homes, 178 Infirmary Road, Sheffield, S6 1QW
Type of notice served:	Enforcement
Details:	Failure to take general fire precautions to ensure the premises are safe for "relevant persons" who are not your employees. Failure to make a suitable and sufficient risk assessment. Failure to provide a fire safety policy document. Failure to ensure that, in the event of danger, it is possible for persons to evacuate the premises as quickly and as safely as possible. The structural fire precautions are inadequately maintained. Failure to maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, firefighters on your premises.
Reference No	EN/W/104
Date of compliance of notice:	<b>09/11/2010</b>

Date on which notice served:	10/09/2010
Name of Organisation:	3 Play Club (Also licensed as Langtons Billiard Hall), 445 London Road, Sheffield, S2 4HJ
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment was not available at the time of the

	<p>inspection.</p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>A fire safety policy document has not been prepared.</p> <p>The escape routes were obstructed.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/W/103
Date of compliance of notice:	<b>02/12/2010</b>

Date on which notice served:	06/09/2010
Name of Organisation:	CEX, 27-29 High Street, Sheffield, S1 2GA
Type of notice served:	Prohibition
Details:	Unsatisfactory Means of Escape
Reference No	PN/W5523/0/101
Date of compliance of notice:	<b>22/09/2010</b>

Date on which notice served:	03/09/2010
Name of Organisation:	Velocity Management Limited, Tenter Street/Solly Street, Sheffield, S1
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>A fire safety policy document has not been prepared.</p> <p>The fire detection system is inadequate.</p> <p>The fire fighting equipment is inadequate.</p> <p>The escape routes were obstructed.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Emergency doors do not open in the direction of escape.</p> <p>The escape routes were not provided with adequate signage.</p> <p>The escape routes were not adequately lit.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Safety training to employees is not repeated periodically.</p> <p>To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, firefighters on your premises.</p>
Reference No	EN/W/100
Date of compliance of notice:	<b>10/11/2010</b>

Date on which notice served:	10/08/2010
Name of Organisation:	Flockton Court, Westfield Terrace, Sheffield, S1 2GH
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document has not been prepared.</p> <p>The fire warning system is inadequate.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>To provide comprehensible and relevant information to employees on persons nominated for fire fighting on the premises and/or assist in evacuation procedures from the premises.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, fire-fighters on your premises.</p>
Reference No	EN/W/96
Date of compliance of notice:	<b>18/10/2010</b>

Date on which notice served:	04/08/2010
Name of Organisation:	23-25 Stevenson Road, Sheffield, S9 3XG
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and ensure the safety of persons who are not their employees.</p> <p>The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p>
Reference No	EN/W/97
Date of compliance of notice:	<b>11/10/2010</b>

Date on which notice served:	07/07/2010
Name of Organisation:	Remar UK, 158-160 Matilda Street, Sheffield, S1 4QG
Type of notice served:	Enforcement
Details:	<p>A Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document was not available at the time of the visit.</p> <p>The fire detection and fire warning systems are inadequate.</p> <p>The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>The escape routes were not adequately lit.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>There were insufficient numbers of competent persons appointed to assist in undertaking preventive and protective measures.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Inadequate safety training is provided to enable to employees to safeguard themselves and other persons on the premises.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/W/94
Date of compliance of notice:	<b>29/09/2010</b>

Date on which notice served:	07/07/2010
Name of Organisation:	Banners Building, 620 Attercliffe Road, Sheffield, S9 3QS
Type of notice served:	Enforcement
Details:	The escape routes were obstructed. The escape routes and exits could not be used as quickly and as safely as possible. The escape routes were not adequately lit. The fire fighting equipment is not easily accessible. The structural fire precautions are inadequately maintained.
Reference No	EN/W/93
Date of compliance of notice:	<b>16/09/2010</b>

Date on which notice served:	02/07/2010
Name of Organisation:	Static, 52-54 West Street, Sheffield, S1 4EP
Type of notice served:	Enforcement
Details:	Inadequate co-ordination with other responsible persons sharing the same means of escape route to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN/W/83
Date of compliance of notice:	<b>04/08/2010</b>

Date on which notice served:	30/06/2010
Name of Organisation:	Costcutter, 6 St Johns Road, Castle Court, Sheffield, S2 5JX
Type of notice served:	Enforcement
Details:	The escape routes were obstructed. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/W/92
Date of compliance of notice:	<b>10/08/2010</b>

Date on which notice served:	18/06/2010
Name of Organisation:	The Albion, 71-75 London Road, Sheffield
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire safety Risk Assessment was not available at the time of the inspection. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. A fire safety policy document was not available at the time of the visit. The risks from a dangerous substance have not been eliminated and/or reduced and/or replaced so far as is reasonably practicable. The fire fighting equipment is inadequate. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. The manual fire fighting equipment is inadequately maintained. The structural fire precautions are inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to enable the employees to

	safeguard themselves and other persons on the premises.
Reference No	EN/12.10/11
Date of compliance of notice:	<b>23/08/2013</b>

Date on which notice served:	15/06/2010
Name of Organisation:	Hi Point Scaffolding Limited, Unit 7 Valley Business Park, Grange Lane, Ecclesfield, Sheffield, S5 0DP
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The Fire Safety Policy document was not suitable and sufficient. The Fire warning system is inadequate. The escape routes were obstructed. The escape routes were not provided with adequate signage. The escape routes were not adequately lit. The manual fire fighting equipment is inadequately maintained. The emergency lighting is inadequately maintained. Safety training to employees is not repeated periodically.
Reference No	En/11.10/11
Date of compliance of notice:	<b>26/08/2010</b>

Date on which notice served:	15/06/2010
Name of Organisation:	Artisan Property Group, Wicker Riverside Apartments, The Wicker, Sheffield, S3 8JD
Type of notice served:	Enforcement
Details:	Failure to take general precautions to ensure the premises are safe for 'relevant persons' who are not your employees. Failure to make a suitable and sufficient risk assessment. Failure to make and give effect to such arrangements as are appropriate for the effective planning, organisation, control, monitoring and review of the preventative and protective measures. Failure to ensure that the premises are, to the extent that it is appropriate, equipped with appropriate fire fighting equipment. Failure to ensure that, in the event of danger, it is possible for persons to evacuate the premises as quickly and safely as possible. Failure to ensure that the premises and/or any facilities, equipment and devices provided in connection with general fire precautions, are suitably maintained.
Reference No	EN/09.10/11
Date of compliance of notice:	<b>28/10/2010</b>

Date on which notice served:	14/06/2010
Name of Organisation:	Penistone Road Trading Estate
Type of notice served:	Enforcement
Details:	The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN10.10/11
Date of compliance of notice:	<b>01/07/2010</b>

Date on which notice served:	10/06/2010
Name of Organisation:	The White Building, Fitzalan Square, Sheffield, S1 2AZ
Type of notice served:	Enforcement

Details:	The Fire Safety Risk Assessment has not been reviewed on a regular basis. To take such general precautions as will ensure the safety of persons who are not his employees. Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN/08.10/11
Date of compliance of notice:	<b>31/08/2010</b>

Date on which notice served:	07/06/2010
Name of Organisation:	Pizza Hut, 10 The Oasis, Meadowhall Centre, Sheffield, S9 1EP
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. Preventative and Protective Measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. To provide comprehensive and relevant information to employees on preventative and protective measures.
Reference No	EN/07.10/11
Date of compliance of notice:	<b>05/07/2010</b>

Date on which notice served:	04/06/2010
Name of Organisation:	Parson Cross Hotel, Deerlands Road, Sheffield, S5 8AA
Type of notice served:	Enforcement
Details:	The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/03.10/11
Date of compliance of notice:	<b>10/08/2010</b>

Date on which notice served:	03/06/2010
Name of Organisation:	CEX, 27-29 High Street, Sheffield, S1 2GA
Type of notice served:	Enforcement
Details:	The escape routes and exits could not be used as quickly and safely as possible. The escape routes were not adequately lit. The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.
Reference No	EN/06.10/11
Date of compliance of notice:	<b>22/09/2010</b>

Date on which notice served:	03/06/2010
Name of Organisation:	The Balti King, 216 Fulwood Road, Sheffield, S10 3BB
Type of notice served:	Enforcement
Details:	A fire safety risk assessment has not been carried out. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. There were insufficient numbers of competent persons appointed to assist in undertaking preventative and protective measures. Inadequate safety training is provided to employees at the time when they are first employed.



Reference No	EN/05.10/11
Date of compliance of notice:	<b>10/11/2010</b>

Date on which notice served:	03/06/2010
Name of Organisation:	King Edward VII Lower School, Darwin Lane, Sheffield, S10 5RG
Type of notice served:	Enforcement
Details:	A fire safety risk assessment has not been carried out. There were insufficient numbers of competent persons appointed to assist in undertaking preventative and protective measures. Safety training to employees is not repeated periodically. Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN/04.10/11
Date of compliance of notice:	<b>05/08/2010</b>

Date on which notice served:	21/05/2010
Name of Organisation:	Parsons Cross Hotel, Deerlands Avenue, Sheffield, S5 8AA
Type of notice served:	Prohibition
Details:	The exit doors from the Function Room are not easily openable. The Function Room is not to be used for any purpose other than repair to the final exit doors.
Reference No	PN/W/01.10/11
Date of compliance of notice:	<b>02/06/2010</b>

Date on which notice served:	20/05/2010
Name of Organisation:	Firth Rixon Metals Limited, Johnson Lane, Ecclesfield, Sheffield S35 9XH
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of the employees. The fire safety policy document was not suitable and sufficient. Arrangements for the safe handling and/or storage and/or transport of dangerous substances and/or waste containing dangerous substances are inadequate. The fire warning system is inadequate. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not provided with adequate signage. The escape routes did not lead, as directly as possible, to a place of safety. Safety training to employees is not repeated periodically.
Reference No	EN/02. 10/11
Date of compliance of notice:	<b>01/12/2010</b>

Date on which notice served:	30/04/2010
Name of Organisation:	Static, 52-54 West Street, Sheffield, S1 4EP
Type of notice served:	Enforcement
Details:	The escape routes were obstructed.
Reference No	EN01.10/11
Date of compliance of notice:	<b>02/07/2010</b>

Date on which notice served:	27/03/2010
Name of Organisation:	Karaoke/Licensed Bar, 100-108 John Street, Sheffield, S2 4QU
Type of notice served:	Prohibition
Details:	Unsatisfactory means of escape from the area of the premises being used for purposes of public entertainment, in conjunction with a number of hazards including gas cylinders, flammable solvents and high fire loading in the public areas and escape routes.
Reference No	PN/W/01/10
Date of compliance of notice:	<b>25/11/2011</b>

Date on which notice served:	19/03/2010
Name of Organisation:	Torlane Services Ltd, Arnold House, 115 Blackburn Road, Rotherham S61 2DW
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and the safety of persons who are not his employees. The fire risk assessment was not suitable and sufficient.</p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>The fire safety policy document was not suitable and sufficient.</p> <p>The measures to control the risks and/or mitigate the detrimental effect of fire from a dangerous substance is not in accordance with the measures specified in Part 4 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>Arrangements for the safe handling and/or storage and/or transport of dangerous substances and/or waste containing dangerous substances is inadequate.</p> <p>The fire warning system is inadequate.</p> <p>Some of the escape routes were obstructed.</p> <p>The escape routes were not provided with adequate signage.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Insufficient competent persons have been nominated to carry out evacuation procedures.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>There were insufficient numbers of competent persons appointed to assist in undertaking preventive and protective measures.</p> <p>To provide comprehensible and relevant information to employees on preventive and protective measures.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Every employee must, while at work, take reasonable care for the safety of himself and others, co-operated with his/her employer or any other employee with specific responsibility for the safety of his/her fellow employees of any hazard.</p>
Reference No	EN/08.09/10
Date of compliance of notice:	<b>06/09/2010</b>

Date on which notice served:	17/12/2009
Name of Organisation:	Zion, 387 Attercliffe Road, Sheffield, S9 3QU
Type of notice served:	Enforcement

Details:	A Fire Risk Assessment has not been carried out. The escape routes did not lead, as directly as possible to a place of safety. The Structural Fire Precautions are inadequately maintained.
Reference No	EN/07.09.10
Date of compliance of notice:	<b>08/06/2010</b>

Date on which notice served:	17/12/2009
Name of Organisation:	Market Inn, 18 Wortley Road, High Green, Sheffield S35 4LU
Type of notice served:	Enforcement
Details:	A fire safety risk assessment has not been carried out. The escape routes were obstructed. The structural fire precautions are inadequately maintained. The fire alarm and emergency lighting are inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN/06.09/10
Date of compliance of notice:	<b>23/02/2010</b>

Date on which notice served:	16/12/2009
Name of Organisation:	Horse and Groom, 426 Blackstock Road, Sheffield S14 1JE
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and the safety of persons who are not his employees. A fire risk assessment was not available at the time of the inspection. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. The escape routes were obstructed. The escape routes and exits could not be used as quickly and safely as possible. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not adequately lit. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The fire alarm system and emergency lighting is inadequately maintained.
Reference No	EN/05.09/10
Date of compliance of notice:	<b>08/02/2010</b>

Date on which notice served:	09/10/2009
Name of Organisation:	Portland Works, Randall Street/Hill Street, Sheffield, S2 4SJ
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A fire safety risk assessment has not been carried out. A Fire Safety Policy document has not been prepared. The risks from a dangerous substance have not been eliminated and/or reduced and/or replaced so far as is reasonably practicable. The escape routes and exits could not be used as quickly and safely as possible.

	The structural fire precautions are in adequately maintained. The fire alarm system is inadequately maintained.
Reference No	EN/04.09/10
Date of compliance of notice:	

Date on which notice served:	03/08/2009
Name of Organisation:	H & H Wholesale, Unit 10, Park House Lane, Sheffield, S19 1XA
Type of notice served:	Enforcement
Details:	Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety Order 2005). The fire warning system is inadequate. The structural fire precautions are inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises. Safety training to employees is not repeated periodically.
Reference No	EN/03.09/10
Date of compliance of notice:	<b>16/02/2010</b>

Date on which notice served:	20/07/2009
Name of Organisation:	WH Smith, 38-40 Fargate, Sheffield S1 2HE
Type of notice served:	Enforcement
Details:	The structural fire precautions are inadequately maintained.
Reference No	EN/02.09/10
Date of compliance of notice:	<b>08/10/2009</b>

Date on which notice served:	21/04/2009
Name of Organisation:	Glastonbury Guest House, 116-118 Abbeyfield Road, Sheffield S4 7AY
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment has not been reviewed on a regular basis. The fire fighting equipment is not easily accessible. The escape routes were obstructed. The escape routes and exits could not be used as quickly and as safely as possible. The Structural Fire Precautions are in adequately maintained. The Fire Alarm System and Emergency Lighting Systems are in adequately maintained. Inadequate Safety Training is provided to employees at the time when they are first employed. Inadequate Safety Training is provided to enable the employees to safeguard themselves and other persons on the premises.
Reference No	EN/04/09
Date of compliance of notice:	<b>20/05/2009</b>

Date on which notice served:	30/03/2009
Name of Organisation:	Royal Mail, Sheffield East Delivery Officer, 734-736 Attercliffe Road, Sheffield, S9 3RR
Type of notice served:	Enforcement

Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The Fire Alarm System is inadequately maintained. The Emergency Lighting System is inadequately maintained. Inadequate Safety Training is provided to employees at the time when they are first employed. Safety Training to employees is not repeated periodically.
Reference No	EN/03/09
Date of compliance of notice:	<b>01/05/2009</b>

Date on which notice served:	23/03/2009
Name of Organisation:	East House, 18 Spital Hill, Sheffield S4 7LG
Type of notice served:	Enforcement
Details:	A Fire Risk Assessment has not been carried out. The Fire Detection System and Fire Warning System are inadequate. The Manual Fire fighting Equipment is inadequately maintained. The Emergency Lighting is inadequately maintained. Inadequate Safety Training is provided to enable the employees to safeguard themselves and other persons on the premises. Safety Training to employees is not repeated periodically.
Reference No	EN/02/09
Date of compliance of notice:	<b>29/06/2009</b>

Date on which notice served:	05/03/2009
Name of Organisation:	Royal Mail, West Delivery Officer, 175 Tupton Hill Road, Sheffield S10 1BQ
Type of notice served:	Enforcement
Details:	The Fire Risk Assessment was not suitable and sufficient. The Structural Fire Precautions are inadequately maintained. The Manual Fire fighting Equipment is inadequately maintained. The Emergency Lighting System is inadequately maintained.
Reference No	EN/01/09
Date of compliance of notice:	<b>05/05/2009</b>