

South Yorkshire Fire and Rescue



Sheffield District - Public Register of Notices Served – April 2017 to March 2019

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	28 th January 2018
Name of Organisation:	St James House, Vicar Lane, Sheffield City Centre, Sheffield S1 2EX
Premises Type:	Office
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p>
Reference No:	EN/W/617
Date of compliance of notice:	

Date on which notice served:	18 th January 2019
Name of Organisation:	52 Upperthorpe Road, Sheffield S6 3EB
Premises Type:	Sleeping Accommodation above Takeaway
Type of notice served:	Enforcement
Details:	<p>The matters which (if the change(s) identified below are made to the premises or the use to which they are put) may constitute a serious risk to relevant persons are:</p> <ul style="list-style-type: none"> • Unsatisfactory means of escape from the 1st and 2nd floor sleeping accommodation. <p><u>Change(s) referred to above which may constitute a risk</u></p> <p>You must notify this Authority before you:</p> <p>Change the use of the premises to allow the 1st and 2nd floors to be used for any other purpose than storage and retrieval or to undertake remedial work as agreed by the authority in pursuance with the removal of this notice.</p>
Reference No:	
Date of compliance of notice:	

Date on which notice served:	8 th January 2019
Name of Organisation:	Beijing House, 141 London Road, Sheffield S2 4LE
Premises Type:	Restaurant/Takeaway with Living and Sleeping Accommodation
Type of notice served:	Alterations
Details:	<p>The matters which if the change(s) identified below are made to the premises or the use to which they are put may constitute a serious risk to relevant persons are:</p> <ul style="list-style-type: none"> • Insufficient fire resisting separation between the sleeping accommodation on the First and Second Floors and restaurant kitchen, and no protected means of escape from the sleeping accommodation through to the final exit at the rear of the ground floor kitchen. • Inadequate means for giving warning in the event of fire. <p><u>Change(s) referred to above which may constitute a risk</u></p> <p>You must notify this Authority before you:</p> <p>Change the use of the premises to allow the First and Second Floors to be used for any other purpose other than storage and retrieval or to undertake remedial work, agreed with this Authority, in pursuance with the removal of this notice.</p>
Reference No:	IN/W/616
Date of compliance of notice:	

Date on which notice served:	19 th December 2019
Name of Organisation:	Century Park, 109 Station Road, Holbrook Industrial Estate, Sheffield S20 3GT
Premises Type:	Office
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>Article 11 (2) The fire safety arrangements have not been recorded.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (a) The escape routes did not lead, as directly as possible, to a place of safety.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p>

	<p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained.</p> <p>Article 22 (1) (c) Failure to inform other responsible persons sharing the same premises of the risks arising out of, or in connection with, your undertaking.</p>
Reference No:	EN/W/612
Date of compliance of notice:	

Date on which notice served:	7 th December 2018
Name of Organisation:	Oak Amusements, 11 Sicey Avenue, Sheffield S5 6NS
Premises Type:	Amusement Arcade
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 11 (1) & (2) Evidence that suitable fire safety arrangements are in place was not available at the time of the visit.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 13 (1) (a) & 13 (2) The firefighting equipment is inadequate.</p> <p>Article 13 (1) (b) & 13 (2) The firefighting equipment is not easily accessible.</p> <p>Article 13 (3) (c) Necessary contacts with external emergency services have not been arranged.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 15 (1) (b) & 15 (3) Insufficient competent persons have been nominated to carry out evacuation procedures.</p> <p>Article 17 (1) The manual firefighting equipment is inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained.</p> <p>Article 19 (1) (b) To provide comprehensible and relevant information to employees on preventive and protective measures.</p> <p>Article 19 (1) (c) To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger.</p>

	<p>Article 19 (1) (d) To provide comprehensible and relevant information to employees on persons nominated for firefighting on the premises and/or assist in evacuation procedures from the premises.</p> <p>Article 21 (1) (a) Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Article 21 (2) (b) Safety training to employees is not repeated periodically.</p>
Reference No:	EN/W/610
Date of compliance of notice:	

Date on which notice served:	6 th December 2018
Name of Organisation:	Whitecroft Works, 67-69 Furnace Hill, Sheffield S3 7AH
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 11 (1) & (2) Evidence that suitable fire safety arrangements are in place was not available at the time of the visit.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 22 Co-operation and Co-ordination.</p>
Reference No:	EN/W/611
Date of compliance of notice:	

Date on which notice served:	21 st November 2018
Name of Organisation:	The Crown Inn, 21 Meadowhall Road, Sheffield S9 1BS
Premises Type:	Public House and Sleeping Accommodation
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 15 (2) (a) Insufficient information was made available to persons in the event of serious and/or imminent danger.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained.</p>
Reference No:	EN/W/608
Date of compliance of notice:	

Date on which notice served:	15 th November 2018
Name of Organisation:	Sheffield Teaching Hospitals Foundation Trust, Sir Robert Hadfield Building, Northern General Hospital, Herries Road, Sheffield S5 7AU
Premises Type:	Hospital
Type of notice served:	Prohibition
Details:	<p>Due to the inadequate compartmentation to prevent the spread of fire vertically and horizontally within the building and via the external building envelope.</p> <p>The building shall not be occupied or used for the treatment or accommodation of Hospital patients. Access is restricted to that which is necessary for remedial work to be undertaken.</p>
Reference No:	PN/W/607
Date of compliance of notice:	

Date on which notice served:	14 th November 2018
Name of Organisation:	The Crown Inn, 21 Meadowhall Road, Sheffield S9 1BS
Premises Type:	Public House and Sleeping Accommodation
Type of notice served:	Prohibition
Details:	<p>Inadequate means of giving warning in case of fire to persons on the first and second floors.</p> <p>Use of the first and second floor to be used for sleeping or living accommodation at any time and restricts the use of these floors to storage, retrieval and the carrying out of any remedial work.</p>
Reference No:	PN/W/606
Date of compliance of notice:	15th November 2018

Date on which notice served:	24 th September 2018
Name of Organisation:	Pheasant Inn, 30 Trafalgar Road, Sheffield S6 1JY
Premises Type:	Public House
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (a) To take such general fire precautions as will ensure the safety of employees.</p> <p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 11 (1) & (2) A fire safety policy document has not been prepared.</p> <p>Article 14 (1) The escape routes were obstructed.</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained.</p> <p>Article 18 (1) & 18 (5) There were insufficient numbers of competent persons appointed to assist in undertaking preventive and protective measures.</p> <p>Article 19 (1) (a) To provide comprehensible and relevant information to employees on risks identified by the risk assessment.</p> <p>Article 19 (1) (b) To provide comprehensible and relevant information to employees on preventive and protective measures.</p> <p>Article 20 (3) (a) Insufficient information provided to the employer of any employees from an outside undertaking to enable that outside employer to identify the nominated person who implements evacuation procedures.</p>

	<p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Article 21 (2) (b) Safety training to employees is not repeated periodically.</p>
Reference No:	EN/W601
Date of compliance of notice:	17th October 2018

Date on which notice served:	2 nd August 2018
Name of Organisation:	Hallamshire Care Home, 3 Broomhall Road, Sheffield S10 2DN
Premises Type:	Residential Care Home
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (a) To take such general fire precautions as will ensure the safety of employees.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (a) The escape routes did not lead, as directly as possible, to a place of safety.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p>
Reference No:	EN/W/597
Date of compliance of notice:	17th October 2018

Date on which notice served:	13 th July 2018
Name of Organisation:	Muslim Welfare House of Sheffield, 8 Severn Road, Sheffield S10 2SU
Premises Type:	House converted to Flat
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (g) The escape routes were not provided with adequate signage.</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p>

	<p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained.</p>
Reference No:	EN/W/595
Date of compliance of notice:	9th August 2018

Date on which notice served:	13 th July 2018
Name of Organisation:	Muslim Welfare House of Sheffield, 10-12 Severn Road, Sheffield S10 2SU
Premises Type:	Premises open to the Public
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Article 14 (2) (g) The escape routes were not provided with adequate signage.</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained.</p>
Reference No:	EN/W/596
Date of compliance of notice:	9th August 2018

Date on which notice served:	31 st July 2018
Name of Organisation:	Frehiwet Habesha Restaurant, 35 Exchange Street, Sheffield S2 5TR
Premises Type:	Restaurant
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <ul style="list-style-type: none"> • Unsatisfactory means of escape from the lower ground area. • Unsatisfactory means for giving warning to occupants in case of fire.
Reference No:	PN/W/599
Date of compliance of notice:	

Date on which notice served:	25 th June 2018
Name of Organisation:	Double Dragon, 748 Chesterfield Road, Sheffield S8 0SE
Premises Type:	Takeaway
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (1) The escape routes were obstructed.</p> <p>Article 14 (2) (c) The number, distribution and/or size of escape routes and exits is inadequate.</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 22 (1) (c) Failure to inform other responsible persons sharing the same premises of the risks arising out of, or in connection with, your undertaking.</p>
Reference No:	EN/W/592
Date of compliance of notice:	19th October 2018

Date on which notice served:	18th June 2018
Name of Organisation:	Beijing House, 141 London Road, Sheffield S2 4LE
Premises Type:	Takeaway
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 14 (1) The escape routes were obstructed.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 21 (1) (a) Inadequate safety training is provided to employees at the time when they are first employed.</p>
Reference No:	EN/W/589
Date of compliance of notice:	8th January 2019

Date on which notice served:	1 st June 2018
Name of Organisation:	Walkley Cottage, 46 Bolehill Road, Sheffield S6 5DD
Premises Type:	Public House
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate</p> <p>Article 14 (1) The escape routes were obstructed</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises</p> <p>Article 22 (1) (b) Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p>
Reference No:	EN/W/590
Date of compliance of notice:	12th July 2018

Date on which notice served:	14 th May 2018
Name of Organisation:	Muang Beauty Salon, 26 Union Street, Sheffield S1 2JP
Premises Type:	Shop
Type of notice served:	Enforcement
Details:	<p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p>
Reference No:	EN/W/587
Date of compliance of notice:	16th October 2018

Date on which notice served:	27 th April 2018
Name of Organisation:	Eyre Street Multi Storey Car Park, Eyre Street, Sheffield S1 4QW
Premises Type:	Public Car Park
Type of notice served:	Enforcement
Details:	<p>Article 14 (2) (h) The escape routes were not adequately lit.</p> <p>Article 17 (1) The refuge communication system is inadequately maintained.</p>
Reference No:	EN/W/585
Date of compliance of notice:	30th May 2018

Date on which notice served:	15 th May 2018
Name of Organisation:	Muang Beauty Salon, 26 Union Street, Sheffield S1 2JP
Premises Type:	Shop
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>The lack of general fire precautions such as automatic fire alarm and fire detection system and fire resisting construction separating the treatment rooms from the escape route to compensate for the excessive dead end travel distance within the premises.</p> <p>The second floor and the first floor beyond the cross-corridor door should not be used or accessed for anything other than retrieval of items by members of staff or for the purpose of remedial works.</p> <p>The rooms up to the cross corridor door on the first floor may only be used if there are staff on the ground floor to give warning in the event of a fire. If no staff member is present on the ground floor then these rooms must not be used.</p>
Reference No:	PN/W/586
Date of compliance of notice:	

Date on which notice served:	27 th April 2018
Name of Organisation:	Beijing House, 141 London Road, Sheffield S2 4LE
Premises Type:	Restaurant/Takeaway with Living and Sleeping Accommodation
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which will give rise to the said risk are:</p> <p>Insufficient fire resisting separation between the sleeping accommodation on the First and Second Floors and restaurant kitchen, and no protected means of escape from the sleeping accommodation through to the final exit at the rear of the ground floor kitchen.</p> <p>Inadequate means for giving warning in the event of fire.</p>
Reference No:	PN/W/583
Date of compliance of notice:	8th January 2019

Date on which notice served:	9 th March 2018
Name of Organisation:	Scarsdale Grange Nursing Home, Derbyshire Lane, Sheffield S8 9EQ
Premises Type:	Care Home
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 17 (1) The structural and passive fire precautions are inadequately maintained.</p> <p>Article 18 (1) & 18 (5) There were insufficient numbers of competent persons appointed to assist in undertaking preventive and protective measures.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/573
Date of compliance of notice:	20th June 2018

Date on which notice served:	2 nd March 2018
Name of Organisation:	The Printworks, 85-95 Headford Street, Sheffield S3 7WA
Premises Type:	Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 11 (1) & (2) The fire safety arrangements are not suitable and sufficient</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The manual fire fighting equipment is inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 38 (1), (2), (3), (4) & (5) To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, fire-fighters on your premises</p>
Reference No:	EN/W/571
Date of compliance of notice:	27th April 2018

Date on which notice served:	6 th March 2018
Name of Organisation:	Ginseng Korean BBQ Restaurant, Unit 12 West One, Fitzwilliam Street, Sheffield S1 4JB
Premises Type:	Licensed Restaurant
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is:</p> <p>The use of the premises for sleeping and the means of escape staircase for storage of combustible items.</p> <p>The lack of general fire precautions including unsatisfactory means of escape and means for giving warning which make this area unsuitable for its current use.</p>
Reference No:	PN/W/572
Date of compliance of notice:	19th July 2018

Date on which notice served:	13 th February 2018
Name of Organisation:	Ginseng Korean BBQ Restaurant, Unit 12 West One, Fitzwilliam Street, Sheffield S1 4JB
Premises Type:	Licensed Restaurant
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is:</p> <p>The use of the means of escape staircase for sleeping and the storage of combustible items</p> <p>The staircase from the first floor to ground level should not be used for sleeping or to store combustible items.</p>
Reference No:	PN/W/568
Date of compliance of notice:	6th March 2018

Date on which notice served:	18 th January 2018
Name of Organisation:	Mayfair Court, 120 West Bar, Sheffield S3 2SQ
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 11 The arrangements for planning, organisation, control, monitoring and review of the preventative and protective measures are not evidenced.</p> <p>Article 14 (1) The escape routes were obstructed.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 14 (2) (h) The escape routes were not adequately lit.</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 22 Where two or more Responsible Persons share, or have duties in respect of, premises each such person must co-operate with the other Responsible Person concerned so far as is necessary to enable them to comply with the requirements and prohibitions imposed on them by or under this Order.</p>
Reference No:	EN/W/559
Date of compliance of notice:	29th May 2018

Date on which notice served:	11 th January 2018
Name of Organisation:	474 Middlewood Road, Sheffield S6 1TQ
Premises Type:	Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 11 (1) & (2) The fire safety arrangements are not suitable and sufficient.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 22 Where two or more Responsible Persons share, or have duties in respect of, premises each such person must co-operate with the other Responsible Person concerned so far as is necessary to enable them to comply with the requirements and prohibitions imposed on them by or under this Order.</p>
Reference No:	EN/W/558
Date of compliance of notice:	26th February 2018

Date on which notice served:	30 th January 2018
Name of Organisation:	52 Upperthorpe Road, Sheffield S6 3EB
Premises Type:	Sleeping Accommodation above Takeaway
Type of notice served:	Restriction
Details:	<p>Unsatisfactory means of escape from the 1st and 2nd floor sleeping accommodation.</p> <p>Unsatisfactory means for raising the alarm in the event of fire.</p> <p>The 1st and 2nd floors to be used for storage and retrieval of personal items only, for carrying out remedial works required to address the matters detailed above.</p>
Reference No:	PN/W/560
Date of compliance of notice:	18th January 2019

Date on which notice served:	13 December 2017
Name of Organisation:	Muang Beauty Salon, 26 Union Street, Sheffield S1 2JP
Premises Type:	Shop
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 10 Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection alarm system is inadequate.</p> <p>Article 13 (3) (a) Measures for fire fighting in the premises is inadequate.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/557
Date of compliance of notice:	14th May 2018

Date on which notice served:	7 December 2017
Name of Organisation:	The Print and Copy Shop, 23 Taplin Road, Hillsborough, Sheffield S6 4JD
Premises Type:	Shop
Type of notice served:	Enforcement
Details:	<p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 22 Article 22 of the Regulatory Reform Fire Safety Order 2005 requires that persons who share, or have duties in respect of, premises co-operate and co-ordinate measures to comply with the requirements of this order. Where the measures detailed above required such cooperation you must ensure that this takes place.</p>
Reference No:	EN/W/554
Date of compliance of notice:	6th February 2018

Date on which notice served:	21 November 2017
Name of Organisation:	Heeley Bank Care Home, Heeley Bank Road, Sheffield S2 3GL
Premises Type:	Care Home
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 17 (1) The structural and passive fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 18 (1) & 18 (5) There were insufficient numbers of competent persons appointed to assist in undertaking preventive and protective measures.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/547
Date of compliance of notice:	20th April 2017

Date on which notice served:	8 December 2017
Name of Organisation:	Muang Beauty Salon, 26 Union Street, Sheffield S1 2JP
Premises Type:	Shop
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>The lack of general fire precautions such as automatic fire alarm and fire detection system and fire resisting construction separating the treatment rooms from the escape route to compensate for the excessive dead end travel distance within the premises.</p> <p>The second floor and the first floor beyond the cross-corridor door should not be used or accessed for anything other than retrieval of items by members of staff or for the purpose of remedial works.</p> <p>The rooms up to the cross corridor door on the first floor may only be used if there are staff on the ground floor to give warning in the event of a fire. If no staff member is present on the ground floor then these rooms must not be used.</p>
Reference No:	PN/W/555
Date of compliance of notice:	15th May 2018

Date on which notice served:	10 November 2017
Name of Organisation:	Hexagon Student Apartments, 2 Rockingham Lane, Sheffield S1
Premises Type:	Flats/Apartments
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 14 (2) (g) The escape routes were not provided with adequate signage.</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 17 (1) The structural and passive fire precautions are inadequately maintained.</p>
Reference No:	EN/W/546
Date of compliance of notice:	6th February 2018

Date on which notice served:	29 November 2017
Name of Organisation:	Betafence Ltd, No.2 Factory, PO Box 119 Shepcote Lane, Sheffield S9 1TY
Premises Type:	Factory (R)
Type of notice served:	Prohibition
Details:	<p>Inadequate protected means of escape from the roof welfare facilities.</p> <p>The roof welfare facilities are not to be used.</p>
Reference No:	PN.W.551
Date of compliance of notice:	

Date on which notice served:	06 November 2017
Name of Organisation:	Fatima Community Centre, 105 Brunswick Road, Sheffield S3 9LQ
Premises Type:	Other Premises open to the Public (P)
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>Article 11 (1) & (2) A fire safety policy document was not available at the time of the visit.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The manual fire fighting equipment is inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained.</p>
Reference No:	EN/W/545
Date of compliance of notice:	6th March 2018

Date on which notice served:	03 November 2017
Name of Organisation:	Priceless Discount Stores Ltd, 199-201 Crookes, Sheffield S10 1TE
Premises Type:	Shop (N)
Type of notice served:	Enforcement
Details:	<p>Article 17 (1) The structural fire precautions are inadequately maintained.</p>
Reference No:	EN/W/544
Date of compliance of notice:	7th December 2017

Date on which notice served:	03 November 2017
Name of Organisation:	D Printing Services Ltd, T/A The Print and Copy Shop, 23 Taplin Road, Hillsborough, Sheffield S6 4JD
Premises Type:	Shop (N)
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>Article 10 Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>Article 11 (1) & (2) A written record detailing the fire safety arrangements was not available at the time of the inspection.</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Article 21 (1) (b) Inadequate safety training is provided to employees on their being exposed to a new or increased risk.</p>
Reference No:	EN/W/543
Date of compliance of notice:	23rd January 2018

Date on which notice served:	20 November 2017
Name of Organisation:	Hexagon Apartments, 2 Rockingham Lane, Sheffield S1 4FU
Premises Type:	Student Accommodation/Flats (G)
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which will give rise to the said risk are:</p> <p>The shutter being in the closed position (down) at the entrance/exit of Belgravia House, which causes inadequate means of escape for Hexagon Apartments.</p> <p>If the shutter is closed (down) no one is to sleep, relax, or reside in Hexagon Apartments.</p>
Reference No:	PN/W/550
Date of compliance of notice:	4th December 2017

Date on which notice served:	17 October 2017
Name of Organisation:	Metis Apartments, 1 Scotland Street, Sheffield S3 7AT
Premises Type:	Purpose Built Flats (D)
Type of notice served:	Enforcement
Details:	Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.
Reference No:	EN/W/542
Date of compliance of notice:	17th November 2017

Date on which notice served:	18 October 2017
Name of Organisation:	Mandale House, Bailey Street, Sheffield S1 4EH
Premises Type:	Purpose Built Flats (D)
Type of notice served:	Enforcement
Details:	Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient. Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees. Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible. Article 14 (2) (g) The escape routes were not provided with adequate signage. Article 17 (1) The structural fire precautions are inadequately maintained. Article 17 (1) The fire alarm system is inadequately maintained. Article 17 (1) The emergency lighting is inadequately maintained.
Reference No:	EN/W/540
Date of compliance of notice:	17th January 2018

Date on which notice served:	16 October 2017
Name of Organisation:	Metis Apartments, 1 Scotland Street, Sheffield S3 7AT
Premises Type:	Purpose Built Flats (D)
Type of notice served:	Restriction
Details:	The Fire and Rescue Authority are further of the opinion that the matter(s) which will give rise to the said risk is: the storage of refuse in rooms provided for that use, which about the elevation of the building which has been identified as having a flammable external cladding system.
Reference No:	PN/W/541
Date of compliance of notice:	

Date on which notice served:	11 August 2017
Name of Organisation:	Wicker Riverside Development, 2 North Bank, Sheffield, S3 8JT
Premises Type:	Purpose Built Flats (D)
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 38 (1), (2), (3), (4) & (5) To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, fire-fighters on your premises.</p>
Reference No:	EN/W/534
Date of compliance of notice:	18TH October 2017

Date on which notice served:	10 August 2017
Name of Organisation:	Alpine Lodge, Alpine Road, Stocksbridge, Sheffield. S36 1AD
Premises Type:	Care Home (B)
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/533
Date of compliance of notice:	14th September 2017

Date on which notice served:	30 August 2017
Name of Organisation:	Nawroz Restaurant, 72 Spital Hill, Sheffield, S4 7LG
Premises Type:	Restaurant (N)
Type of notice served:	Prohibition
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits</p>
Reference No:	PN.W.537
Date of compliance of notice:	4th October 2017

Date on which notice served:	21 st July 2017
Name of Organisation:	230 Lane End, Chapeltown, Sheffield S35 2UZ
Premises Type:	Sleeping Accommodation (H)
Type of notice served:	Restriction
Details:	<p>There are insufficient means for detection and giving warning to alert occupants to a fire within the premises. A fire on the ground or first floor will result in heat and/or smoke filling the escape route potentially overcoming people or preventing them from making a safe escape from the premises before persons are aware of any fire.</p>
Reference No:	PN/W/531
Date of compliance of notice:	4th October 2017

Date on which notice served:	25 th May 2017
Name of Organisation:	Practice Sheffield, 32 Trinity Street, Sheffield S3 8AJ
	Rehearsal Studio (P)
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) - A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 13 (1) (a) & 13 (2) - The fire detection and alarm system is inadequate.</p> <p>Article 13 (1) (a) & 13 (2) - The fire fighting equipment is inadequate.</p> <p>Article 14 (2) (b) - The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 14 (2) (f) - Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Article 14 (2) (g) - The escape routes were not provided with adequate signage.</p> <p>Article 14 (2) (h) - The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 21 (2) (a) - Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/525
Date of compliance of notice:	29th June 2017

Date on which notice served:	19 th May 2017
Name of Organisation:	Practice Sheffield, 32 Trinity Street, Sheffield S3 8AJ
Premises Type:	Rehearsal Studio (P)
Type of notice served:	Restriction
Details:	<p>Absence of fire detection and means of giving warning in case of fire.</p> <p>Unsatisfactory means of escape due to absence of emergency lighting and an unusable rear exit causing an unsatisfactory travel distance.</p>
Reference No:	EN/W/524
Date of compliance of notice:	31st May 2017

Date on which notice served:	13 th April 2017
Name of Organisation:	CeX, 27-29 High Street, Sheffield S1 2GA
Premises Type:	Shop (N)
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) - The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 14 (1) - The escape routes were obstructed.</p> <p>Article 14 (2) (b) - The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 14 (2) (g) - The escape routes were not provided with adequate signage.</p> <p>Article 17 (1) - The structural and passive fire precautions are inadequately maintained.</p> <p>Article 17 (1) - The fire alarm system is inadequately maintained.</p> <p>Article 21 (2) (a) - Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/521
Date of compliance of notice:	7th June 2017

Date on which notice served:	7 th April 2017
Name of Organisation:	Sheffield Gauge Plate Ltd, Bastock Road, Sheffield S6 2AE
Premises Type:	Factory (R)
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) - A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 12 (4) (a) - Arrangements for the safe handling and/or storage and/or transport of dangerous substances and/or waste containing dangerous substances is inadequate.</p> <p>Article 13 (1) (a) & 13 (2) - The fire warning system is inadequate.</p> <p>Article 14 (1) - The escape routes were obstructed.</p> <p>Article 14 (2) (b) - The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 14 (2) (f) - Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>Article 14 (2) (h) - The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p>Article 17 (1) - The manual fire fighting equipment is inadequately maintained.</p> <p>Article 21 (2) (a) - Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/520
Date of compliance of notice:	18th May 2017