



## South Yorkshire Fire and Rescue

### Sheffield District - Public Register of Notices Served – April 2021 to March 2023

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	21 <sup>st</sup> July 2022
Name of Organisation:	M White Ltd, 65 Worthing Road, Attercliffe, Sheffield, S9 3JA
Premises Type:	Factory/Warehouse
Type of notice served:	Prohibition
Details:	<b>Article 14</b> Unsatisfactory Means of escape from the office building
Reference No:	PN/W/792
Date of compliance of notice:	

Date on which notice served:	28 <sup>th</sup> June 2022
Name of Organisation:	Haythorn Place, 77 Shiregreen Lane, Sheffield S5 6AB
Premises Type:	Nursing Home
Type of notice served:	Enforcement
Details:	<b>Article 9 (1)</b> The Fire Safety Risk Assessment was not suitable and sufficient <b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible <b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place <b>Article 21 (2) (a)</b> Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises
Reference No:	EN/W/786
Date of compliance of notice:	

Date on which notice served:	15 <sup>th</sup> June 2022
Name of Organisation:	Haythorn Place, 77 Shiregreen Lane, Sheffield S5 6AB
Premises Type:	Nursing Home
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (a) and (1) (b)</b> To take such general fire precautions as will ensure the safety of employees and persons who are not his employees</p> <p><b>Article 9 (1)</b> The Fire Safety Risk Assessment was not suitable and sufficient</p> <p><b>Article 10</b> Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> The fire detection and warning system is inadequate</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><b>Article 17 (1)</b> The structural fire precautions are inadequately maintained</p>
Reference No:	EN/W/784
Date of compliance of notice:	
Date on which notice served:	28 <sup>th</sup> May 2022
Name of Organisation:	Wicker Lounge, 122-126 Wicker Street, Sheffield, S3 8JD
Premises Type:	Licensed
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Provide suitable means for detecting fire and giving warning in case of fire.</p>
Reference No:	PN/W/783
Date of compliance of notice:	

Date on which notice served:	8 <sup>th</sup> April 2022
Name of Organisation:	Riverside Apartments, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 22 (1) (a) &amp; (1) (b)</b> Inadequate co-operation and co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p>
Reference No:	EN/W/768 - EN/W/773 - EN/W/774
Date of compliance of notice:	

Date on which notice served:	8 <sup>th</sup> April 2022
Name of Organisation:	Riverside Apartments, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 22 (1) (a) &amp; (1) (b)</b> Inadequate co-operation and co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p>
Reference No:	EN/W/767 - EN/W/771 - EN/W/772
Date of compliance of notice:	

Date on which notice served:	8 <sup>th</sup> April 2022
Name of Organisation:	Riverside Apartments, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p><b>Article 9 (1)</b> The Fire Safety Risk Assessment was not suitable and sufficient</p> <p><b>Article 22 (1) (a) &amp; (1) (b)</b> Inadequate co-operation and co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p>
Reference No:	EN/W/766 - EN/W/769 - EN/W/770
Date of compliance of notice:	
Date on which notice served:	29 <sup>th</sup> April 2022
Name of Organisation:	Rowsha Restaurant, 288 South Road, Sheffield S6 3TE
Premises Type:	Licensed Restaurant
Type of notice served:	Alterations
Details:	South Yorkshire Fire and Rescue Authority is of the opinion that the premises constitute a serious risk to relevant persons if the premises are used as sleeping accommodation and/or living accommodation at any time by any person. All basement areas are to be used for the storage and retrieval of Restaurant stock items only.
Reference No:	IN/W/777
Date Notice Withdrawn:	

Date on which notice served:	27 <sup>th</sup> April 2022
Name of Organisation:	Concord Carpets and Flooring, 440 Bellhouse Road, Sheffield S5 0RF
Premises Type:	Shop with Flat Above
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Inadequate means of escape, inadequate means of detection and warning</p>
Reference No:	PN/W/778
Date of compliance of notice:	

Date on which notice served:	27/04/2022
Name and Address of Premises:	Best Western Cutlers Hotel, George Street, Sheffield S1 2PF
Premises Type:	Hotel
Type of notice served:	Alterations
Details:	<p><b>Article 8 (1) (a)</b> To take such general fire precautions as will ensure the safety of employees and persons who are not his employees.</p> <p><b>Article 9 (3) (a)</b> The Fire Safety Risk Assessment has not been reviewed on a regular basis.</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> The fire detection system is inadequate.</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible.</p> <p><b>Article 14 (2) (d)</b> Emergency doors do not open in the direction of escape.</p> <p><b>Article 14 (2) (h)</b> The escape routes were not adequately lit</p> <p><b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p><b>Article 17 (1)</b> The emergency lighting is inadequately maintained</p>
Reference No:	IN/W/776
Date Notice Withdrawn:	

Date on which notice served:	08/04/2022
Name of Organisation:	Shapla Indian Restaurant, 26-28 Cumberland Street, Sheffield S1 4PX
Premises Type:	Licensed Restaurant
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which gives rise to the said risk is:</p> <p>Inadequate means of detection and warning in the event of a fire</p>
Reference No:	PN/W/775
Date of compliance of notice:	<b>19<sup>th</sup> July 2022</b>

Date on which notice served:	10/03/2022
Address of Premises:	196b Brook Hill Road, Sheffield, S3 7HE
Premises Type:	Ancillary Sleeping above Business Premises
Type of notice served:	Enforcement
Details:	<p><b>Article 9(1)</b> A Fire Safety Risk Assessment has not been carried out.</p> <p><b>Article 11 (1)</b> The fire safety arrangements are not suitable and sufficient.</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> The fire detection system is inadequate. The fire warning system is inadequate.</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible.</p> <p><b>Article 14 (2) (f)</b> Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p><b>Article 14 (2) (h)</b> The escape routes were not adequately lit.</p>
Reference No:	EN/W/760
Date of compliance of notice:	

Date on which notice served:	10/03/2022
Address of Premises:	198b Brook Hill Road, Sheffield, S3 7HE
Premises Type:	Ancillary Sleeping above Business Premises
Type of notice served:	Enforcement
Details:	<p><b>Article 9(1)</b> A Fire Safety Risk Assessment has not been carried out.</p> <p><b>Article 11 (1)</b> The fire safety arrangements are not suitable and sufficient.</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> The fire detection system is inadequate. The fire warning system is inadequate.</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible.</p> <p><b>Article 14 (2) (f)</b> Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p><b>Article 14 (2) (h)</b> The escape routes were not adequately lit.</p>
Reference No:	EN/W/761
Date of compliance of notice:	

Date on which notice served:	28/02/2022 and 02/03/2022
Name and Address of Premises:	Best Western Cutlers Hotel, George Street, Sheffield S1 2PF
Premises Type:	Hotel
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (a)</b> To take such general fire precautions as will ensure the safety of employees and persons who are not his employees.</p>
Reference No:	EN.W.737, 747, 748, 749, 750, 751, 757, 759 (8 x Enforcements)
Date Notices Withdrawn:	<b>27<sup>th</sup> April 2022</b>

Date on which notice served:	28/02/2022 and 02/03/2022
Name and Address of Premises:	Best Western Cutlers Hotel, George Street, Sheffield S1 2PF
Premises Type:	Hotel
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (a)</b> To take such general fire precautions as will ensure the safety of employees and persons who are not his employees.</p> <p><b>Article 9 (3) (a)</b> The Fire Safety Risk Assessment has not been reviewed on a regular basis.</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> The fire detection system is inadequate.</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible.</p> <p><b>Article 14 (2) (d)</b> Emergency doors do not open in the direction of escape.</p> <p><b>Article 14 (2) (h)</b> The escape routes were not adequately lit</p> <p><b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p><b>Article 17 (1)</b> The emergency lighting is inadequately maintained</p>
Reference No:	EN.W. 738, 740, 741, 742, 743, 744, 753, 756 (8 x Enforcements)
Date Notices Withdrawn:	<b>27<sup>th</sup> April 2022</b>

Date on which notice served:	03/03/2022
Address of Premises:	196b Brook Hill Road, Sheffield, S3 7HE
Premises Type:	Ancillary Sleeping above Business Premises
Type of notice served:	Prohibition
Details:	The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:  Inadequate means of detection and warning of fire Inadequate means of escape
Reference No:	PN/W/758
Date of compliance of notice:	

Date on which notice served:	03/03/2022
Address of Premises:	198b Brook Hill Road, Sheffield, S3 7HE
Premises Type:	Ancillary Sleeping above Business Premises
Type of notice served:	Prohibition
Details:	The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:  Inadequate means of detection and warning of fire Inadequate means of escape
Reference No:	PN/W/755
Date of compliance of notice:	

Date on which notice served:	18/02/2022
Name of Organisation:	Best Western Cutlers Hotel, George Street, Sheffield. S1 2PF
Premises Type:	Hotel
Type of notice served:	Prohibition
Details:	The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:  Inadequate means of escape from the fourth floor Inadequate fire compartmentation
Reference No:	PN/W/734
Date of compliance of notice:	



Date on which notice served:	10/02/2022
Name of Organisation:	Sofa Traders, 151 Richmond Park Road, Sheffield S13 8HR
Premises Type:	Shop
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Unsatisfactory means of escape.</p> <p>Insufficient management procedures for the removal of security devices from emergency escape final exit doors upon store opening.</p>
Reference No:	PN/W/732
Date of compliance of notice:	<b>17<sup>th</sup> February 2022</b>

Date on which notice served:	27/01/2022
Name of Organisation:	Bettys Diner, 276 Gleadless Road, Sheffield S2 3AH
Premises Type:	Cafe
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Unsatisfactory fire compartmentation from the ground floor Diner's ceiling to the first floor sleeping accommodation.</p> <p>Unsatisfactory means of escape from the rear of the building.</p>
Reference No:	PN/W/727
Date of compliance of notice:	<b>4<sup>th</sup> February 2022</b>

Date on which notice served:	15/11/2021
Name of Organisation:	Dibco Precision Engineering Ltd, Belgrave House, 46-54 Balaclava Road, Sheffield S6 3BG
Premises Type:	Factory
Type of notice served:	Enforcement
Details:	<p><b>Article 9 (1)</b> A Fire Safety Risk Assessment has not been carried out.</p> <p><b>Article 10</b> Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> The fire warning system is inadequate</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><b>Article 14 (2) (g)</b> The escape routes were not provided with adequate signage</p> <p><b>Article 14 (2) (h)</b> The escape routes were not adequately lit</p>

	<p><b>Article 14 (2) (h)</b> The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits</p> <p><b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p><b>Article 21 (2) (a)</b> Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises</p>
Reference No:	EN/W/721
Date of compliance of notice:	<b>17<sup>th</sup> February 2022</b>

Date on which notice served:	17/11/2021
Name of Organisation:	Sharrow Vale Hardware, 370-372 Sharrow Vale Road, Sheffield S11 8ZP
Premises Type:	Shop
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which will give rise to the said risk are:</p> <p>Insufficient passive fire safety measures to the means of escape.</p> <p>Insufficient measures in relation to the means for detecting fire and giving warning in case of fire</p>
Reference No:	PN/W/724
Date of compliance of notice:	<b>29<sup>th</sup> November 2021</b>

Date on which notice served:	25/10/2021
Name of Organisation:	Dalbury and Palmer Hotel, 40 Wostenholm Road, Sheffield S7 1LJ
Premises Type:	Hotel
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 9 (1)</b> The Fire Safety Risk Assessment was not suitable and sufficient</p> <p><b>Article 10</b> Combustible items should not be stored in close proximity to ignition sources. The extract system must be subject to a programme of routine maintenance.</p> <p><b>Article 11 (2)</b> The fire safety arrangements have not been recorded</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> The firefighting equipment is inadequate</p> <p><b>Article 13 (3) (b) &amp; 13 (4)</b> Insufficient competent persons have been nominated to implement firefighting measures</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p><b>Article 15 (1) (b) &amp; 15 (3)</b> Insufficient competent persons have been nominated to carry out evacuation procedures</p> <p><b>Article 21 (2) (b)</b> Safety training to employees is not repeated periodically</p>
Reference No:	EN/W/720
Date of compliance of notice:	<b>21<sup>st</sup> February 2022</b>

Date on which notice served:	20/10/2021
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p><b>Article 22 (1) (a) &amp; (1) (b)</b> Inadequate co-operation and co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p>
Reference No:	EN/W/717
Date of compliance of notice:	<b>3<sup>rd</sup> March 2022</b>

Date on which notice served:	20/10/2021
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<b>Article 22 (1) (a) &amp; (1) (b)</b> Inadequate co-operation and co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005
Reference No:	EN/W/718
Date of compliance of notice:	<b>4<sup>th</sup> March 2022</b>

Date on which notice served:	20/10/2021
Name of Organisation:	Wicker Riverside, 203 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<b>Article 22 (1) (a) &amp; (1) (b)</b> Inadequate co-operation and co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005
Reference No:	EN/W/719
Date of compliance of notice:	<b>4<sup>th</sup> March 2022</b>

Date on which notice served:	28/07/2021
Name of Organisation:	Quality Hotels Sheffield North, Lane End, Chapeltown, Sheffield S35 3UH
Premises Type:	Hotel
Type of notice served:	Enforcement
Details:	<b>Article 11 (2)</b> The fire safety arrangements have not been recorded <b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible <b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place <b>Article 17 (1)</b> The passive fire precautions are inadequately maintained <b>Article 17 (1)</b> The manual fire fighting equipment is inadequately maintained <b>Article 17 (1)</b> The fire alarm system is inadequately maintained <b>Article 17 (1)</b> The emergency lighting is inadequately maintained

	<p><b>Article 19 (1) (c)</b> To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger</p> <p><b>Article 21 (2) (a)</b> Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises</p>
Reference No:	EN/W/705
Date of compliance of notice:	

Date on which notice served:	07/07/2021
Name of Organisation:	Brightside Motors Ltd, 90 Holywell Road, Sheffield S4 8AS
Premises Type:	Garage
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (a)</b> To take such general fire precautions as will ensure the safety of employees</p> <p><b>Article 9 (1)</b> A Fire Safety Risk Assessment has not been carried out</p> <p><b>Article 9 (8) (a) &amp; (b)</b> To carry out a new Risk Assessment and/or act on its significant findings regarding a new work activity that involves a dangerous substance</p> <p><b>Article 10</b> Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p><b>Article 11 (2)</b> The fire safety arrangements have not been recorded</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p><b>Article 15 (2) (a)</b> Insufficient information was made available to persons in the event of serious and/or imminent danger</p> <p><b>Article 17 (1)</b> The manual fire fighting equipment is inadequately maintained</p> <p><b>Article 17 (1)</b> The fire alarm system is inadequately maintained</p> <p><b>Article 17 (1)</b> The emergency lighting is inadequately maintained</p> <p><b>Article 21 (2) (a)</b> Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises</p> <p><b>Article 21 (2) (b)</b> Safety training to employees is not repeated periodically</p>
Reference No:	EN/W/704
Date of compliance of notice:	10 <sup>th</sup> November 2021

Date on which notice served:	07/07/2021
Name of Organisation:	Brightside Motors Ltd, 90 Holywell Road, Sheffield S4 8AS
Premises Type:	Garage
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (a)</b> To take such general fire precautions as will ensure the safety of employees</p> <p><b>Article 9 (1)</b> A Fire Safety Risk Assessment has not been carried out</p> <p><b>Article 9 (8) (a) &amp; (b)</b> To carry out a new Risk Assessment and/or act on its significant findings regarding a new work activity that involves a dangerous substance</p> <p><b>Article 10</b> Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p><b>Article 11 (2)</b> The fire safety arrangements have not been recorded</p> <p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><b>Article 15 (1) (a)</b> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p><b>Article 15 (2) (a)</b> Insufficient information was made available to persons in the event of serious and/or imminent danger</p> <p><b>Article 17 (1)</b> The manual fire fighting equipment is inadequately maintained</p> <p><b>Article 17 (1)</b> The fire alarm system is inadequately maintained</p> <p><b>Article 17 (1)</b> The emergency lighting is inadequately maintained</p> <p><b>Article 21 (2) (a)</b> Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises</p> <p><b>Article 21 (2) (b)</b> Safety training to employees is not repeated periodically</p>
Reference No:	EN/W/703
Date of compliance of notice:	10 <sup>th</sup> November 2021

Date on which notice served:	07/07/2021
Name of Organisation:	Former Betafence, No.2 Factory, PO Box 119, Shepcote Lane, Sheffield S9 1TY
Premises Type:	Factory
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Inadequate protected means of escape from the roof top welfare facilities. This situation will result in relevant persons being trapped by products of fire and smoke.</p>
Reference No:	PN/W/706
Date of compliance of notice:	

Date on which notice served:	09/06/2021
Name of Organisation:	Wicker Riverside, 2-3 Northbank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 9 (1)</b> The Fire Safety Risk Assessment was not suitable and sufficient</p> <p><b>Article 38 (1), (2), (3), (4) &amp; (5)</b> To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, fire-fighters on your premises</p>
Reference No:	EN/W/701
Date of compliance of notice:	<b>4<sup>th</sup> March 2022</b>

Date on which notice served:	09/06/2021
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 9 (1)</b> The Fire Safety Risk Assessment was not suitable and sufficient</p> <p><b>Article 38 (1), (2), (3), (4) &amp; (5)</b> To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, fire-fighters on your premises</p>
Reference No:	EN/W/700
Date of compliance of notice:	<b>3<sup>rd</sup> March 2022</b>

Date on which notice served:	09/06/2021
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 9 (1)</b> The Fire Safety Risk Assessment was not suitable and sufficient</p> <p><b>Article 38 (1), (2), (3), (4) &amp; (5)</b> To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, fire-fighters on your premises</p>
Reference No:	EN/W/699
Date of compliance of notice:	<b>4<sup>th</sup> March 2022</b>

Date on which notice served:	29/06/2021
Name of Organisation:	Quality Hotels Sheffield North, Lane End, Chapeltown, Sheffield S35 3UH
Premises Type:	Hotel
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is:</p> <p>Inadequate means of detection and warning of fire throughout the premises.</p> <p>This situation would permit a fire to go undetected to any sleeping occupants of the premises.</p>
Reference No:	PN/W/702
Date of compliance of notice:	<b>1<sup>st</sup> July 2021</b>

Date on which notice served:	15/04/2021
Name of Organisation:	Agha Lounge Limited, 5 North Bank, Sheffield S3 8JT
Premises Type:	Restaurant/Bar
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is:</p> <p>Flammable elements within the external wall system, which allow potential for rapid fire spread around the building which could place relevant persons at risk of death or serious injury within the apartments.</p> <p>Patio heaters, any other kind of heater or naked flame are not to be used in the vicinity of the premises at any time.</p>
Reference No:	PN/W/693
Date of compliance of notice:	



Date on which notice served:	6 <sup>th</sup> April 2021
Name of Organisation:	St James House, Vicar Lane, Sheffield S1 2EX
Premises Type:	Office Block
Type of notice served:	Enforcement
Details:	<p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><b>Article 17 (1)</b> The passive fire precautions are inadequately maintained</p>
Reference No:	EN/W/688
Date of compliance of notice:	<b>26<sup>th</sup> November 2021</b>

Date on which notice served:	6 <sup>th</sup> April 2021
Name of Organisation:	St James House, Vicar Lane, Sheffield S1 2EX
Premises Type:	Office Block
Type of notice served:	Enforcement
Details:	<p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p>
Reference No:	EN/W/689
Date of compliance of notice:	

Date on which notice served:	6 <sup>th</sup> April 2021
Name of Organisation:	St James House, Vicar Lane, Sheffield S1 2EX
Premises Type:	Office Block
Type of notice served:	Enforcement
Details:	<p><b>Article 14 (2) (b)</b> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><b>Article 17 (1)</b> The structural fire precautions are inadequately maintained</p>
Reference No:	EN/W/690
Date of compliance of notice:	<b>17<sup>th</sup> August 2022</b>

Date on which notice served:	6 <sup>th</sup> April 2021
Name of Organisation:	Kelham Friary, 151-153 Gibraltar Street, Sheffield S3 8UA
Premises Type:	Takeaway
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 22 (1) (b)</b> Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p>
Reference No:	EN/W/691
Date of compliance of notice:	<b>11<sup>th</sup> June 2021</b>

Date on which notice served:	13 <sup>th</sup> April 2021
Name of Organisation:	Kelham Friary, 151-153 Gibraltar Street, Sheffield S3 8UA
Premises Type:	Takeaway
Type of notice served:	Enforcement
Details:	<p><b>Article 8 (1) (b)</b> To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><b>Article 22 (1) (b)</b> Inadequate co-ordination with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p>
Reference No:	EN/W/692
Date of compliance of notice:	<b>11<sup>th</sup> June 2021</b>

Date on which notice served:	7 <sup>th</sup> May 2021
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matters which give rise to the said risk are:</p> <p>There is insufficient fire resisting separation between the car park and the rest of the building, part of the car park ceiling is also lined with a combustible insulation. There is also insufficient fire detection within the car park to enable early warning to support the simultaneous evacuation strategy. Any fire developing in the car park could be spread throughout the building (as seen by the soot/air movement throughout the premises) and make means of escape untenable placing relevant person at risk of death or serious injury, and the Fire and Rescue Authority hereby direct that the use of the premises to which this Notice relates is restricted as follows:</p> <p>The car park should not be used for any reason by any vehicle, until the matters specified above have been remedied.</p>
Reference No:	PN/694
Date of compliance of notice:	

Date on which notice served:	7 <sup>th</sup> May 2021
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matters which give rise to the said risk are:</p> <p>There is insufficient fire resisting separation between the car park and the rest of the building, part of the car park ceiling is also lined with a combustible insulation. There is also insufficient fire detection within the car park to enable early warning to support the simultaneous evacuation strategy. Any fire developing in the car park could be spread throughout the building (as seen by the soot/air movement throughout the premises) and make means of escape untenable placing relevant person at risk of death or serious injury, and the Fire and Rescue Authority hereby direct that the use of the premises to which this Notice relates is restricted as follows:</p> <p>The car park should not be used for any reason by any vehicle, until the matters specified above have been remedied.</p>
Reference No:	PN/695
Date of compliance of notice:	

Date on which notice served:	7 <sup>th</sup> May 2021
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matters which give rise to the said risk are:</p> <p>There is insufficient fire resisting separation between the car park and the rest of the building, part of the car park ceiling is also lined with a combustible insulation. There is also insufficient fire detection within the car park to enable early warning to support the simultaneous evacuation strategy. Any fire developing in the car park could be spread throughout the building (as seen by the soot/air movement throughout the premises) and make means of escape untenable placing relevant person at risk of death or serious injury, and the Fire and Rescue Authority hereby direct that the use of the premises to which this Notice relates is restricted as follows:</p> <p>The car park should not be used for any reason by any vehicle, until the matters specified above have been remedied.</p>
Reference No:	PN/698
Date of compliance of notice:	