

Rotherham District - Public Register of Notices Served – April 2011 to March 2013

Date on which notice served:	29/11/2012
Name of Organisation:	Spice Lounge, 95 Wales Road, Kiveton Park, Sheffield S26 6RA
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. A fire safety policy document has not been prepared. The fire fighting equipment is inadequate. The escape routes were not adequately lit. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN.ND280
Date of compliance of notice:	05/02/2013

Date on which notice served:	04/05/2012
Name of Organisation:	Eastwood View WMC, Fitzwilliam Road, Rotherham S65 1NA
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. There was inadequate information and access to information provided to enable an externally appointed competent person to fulfil their function for the purposes of assisting with preventive and protective measures.
Reference No	EN.ND229
Date of compliance of notice:	30/10/2012

Date on which notice served:	01/05/2012
Name of Organisation:	The Gallows, Hangsman Lane, Laughton Common, Sheffield S25 3PF
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire Safety Risk Assessment has not been carried out. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. A fire safety policy document has not been prepared. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequately safety training is provided to enabled the employees to safeguard themselves and other persons on the premises.
Reference No	EN.ND227
Date of compliance of notice:	14/06/2012

Date on which notice served:	23/02/2012
Name of Organisation:	The Consort Hotel, Brampton road, Thurgroft, Rotherham
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees, and persons who are not his employees. The emergency lighting is inadequately maintained. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. The fire detection system is inadequate.
Reference No	EN.ND203
Date of compliance of notice:	18/04/2012

Date on which notice served:	01/02/2012
Name of Organisation:	Magna Project, Sheffield Road, Templeborough, Rotherham, S60 1DX
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees, and persons who are not his employees. A fire safety risk assessment has not been carried out. The fire fighting equipment is inadequate. The fire fighting equipment is not easily accessible. Insufficient competent persons have been nominated to implement fire fighting measures. The escape routes were obstructed. The escape routes did not lead, as directly as possible, to a place of safety. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not provided with adequate signage. The escape routes were not adequately lit. The number, distribution and/or size of escape routes and exits is inadequate. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises. Safety training to employees is not repeated periodically. To maintain and keep in efficient working order facilities, equipment and devices provided for the use by, or protection of, fire fighters on your premises.
Reference No	EN.ND197
Date of compliance of notice:	01/05/2012

Date on which notice served:	21/12/2011
Name of Organisation:	Tesco PLC
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of

	employees, and persons who are not his employees. The escape routes were obstructed.
Reference No	EN.ND179
Date of compliance of notice:	24/01/2012

Date on which notice served:	13/06/2011
Name of Organisation:	Montrose Furnishings, 42-44 Wellgate, Rotherham, S60 1AS
Type of notice served:	Enforcement Notice
Details:	To take such general fire precautions as will ensure the safety of employees and persons who are not their employees. A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The fire fighting equipment is inadequate. The escape routes were obstructed. The escape routes were not provided with adequate signage. The escape routes were not adequately lit. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.
Reference No	EN.ND132
Date of compliance of notice:	19/12/2011

Date on which notice served:	12/04/2011
Name of Organisation:	Montrose Furnishings, 42-44 Wellgate, Rotherham, S60 1AS
Type of notice served:	Enforcement Notice
Details:	To take such general fire precautions as will ensure the safety of employees and persons who are not their employees. A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The fire fighting equipment is inadequate. The escape routes were obstructed. The escape routes were not provided with adequate signage. The escape routes were not adequately lit. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.
Reference No	EN.ND.128
Date of compliance of notice:	Notice withdrawn