

South Yorkshire Fire and Rescue

Rotherham District - Public Register of Notices Served – April 2017 to March 2019

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	04.05.18
Name of Organisation:	Tachart Ltd/ t/a Bolt & Nut Manufacturing, BnM Building, White Lee Road, Swinton, Mexborough, S64 8BH.
Type of notice served:	Enforcement
Details:	<p><u>Article 8 (1) (a)</u></p> <p>To take such general fire precautions as will ensure the safety of employees.</p> <p><u>Article 10</u></p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p><u>Article 11 (1) & (2)</u></p> <p>A fire safety policy document has not been prepared</p> <p><u>Article 13 (1) (a) & 13 (2)</u></p> <p>The fire detection system is inadequate</p> <p><u>Article 13 (1) (a) & 13 (2)</u></p> <p>The fire warning system is inadequate</p> <p><u>Article 14 (2) (b)</u></p> <p>The escape routes and exits could not be used as quickly and as safely as possible</p> <p><u>Article 14 (2) (f)</u></p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p><u>Article 14 (2) (g)</u></p> <p>The escape routes were not provided with adequate signage</p> <p><u>Article 14 (2) (h)</u></p>

	<p>The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits</p> <p><u>Article 15 (1) (a)</u></p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p><u>Article 15 (1) (b) & 15 (3)</u></p> <p>Insufficient competent persons have been nominated to carry out evacuation procedures</p> <p><u>Article 20 (2)</u></p> <p>Inadequate provision of instruction and/or comprehensible and relevant information on risks to an employee from an outside undertaking</p> <p><u>Article 21 (1) (a)</u></p> <p>Inadequate safety training is provided to employees at the time when they are first employed</p> <p><u>Article 21 (2) (b)</u></p> <p>Safety training to employees is not repeated periodically</p>
Reference No:	EN.ND.584
Date of compliance of notice:	02.11.18

Date on which notice served:	05.04.18
Name of Organisation:	Mega Parts, Ivanhoe Business Park, Wortley Road, Rotherham, S61 1LZ.
Type of notice served:	Enforcement
Details:	<p><u>Article 9 (1)</u></p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p><u>Article 13 (1) (a) & 13 (2)</u></p> <p>The fire detection system is inadequate</p> <p><u>Article 13 (1) (a) & 13 (2)</u></p>

	<p>The fire warning system is inadequate <u>Article 13 (1) (a) & 13 (2)</u></p> <p>The fire fighting equipment is inadequate <u>Article 14 (1)</u></p> <p>The escape routes were obstructed <u>Article 14 (2) (a)</u></p> <p>The escape routes did not lead, as directly as possible, to a place of safety. <u>Article 14 (2) (b)</u></p> <p>The escape routes and exits could not be used as quickly and as safely as possible <u>Article 14 (2) (h)</u></p> <p>The escape routes were not adequately lit <u>Article 15 (1) (a)</u></p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place <u>Article 21 (1) (a)</u></p> <p>Inadequate safety training is provided to employees at the time when they are first employed <u>Article 21 (2) (b)</u></p> <p>Safety training to employees is not repeated periodically</p>
Reference No:	EN.ND.575
Date of compliance of notice:	Withdrawn 15.03.19

Date on which notice served:	04.04.18
Name of Organisation:	Mega Parts, Ivanhoe Business Park, Wortley Road, Rotherham, S61 1LZ.
Type of notice served:	Prohibition
Details:	<u>Article 13</u>

	<p>A suitable fire alarm system conforming to British Standard 5839: Part 1: 2013 or an equivalent standard, should be provided throughout the premises.</p> <p>Fire extinguishers are to be installed within the premises in accordance with British Standard 5306 – 8: 2012 or equivalent standard.</p> <p><u>Article 14</u></p> <p>A suitable emergency lighting system conforming to British Standard 5266: Part 1: 2011. or equivalent standard, should be provided throughout the premises.</p> <p>Sufficient additional final exits are required to reduce travel distance within the premises.</p>
Reference No:	PN.ND.574
Date of compliance of notice:	11.05.18

Date on which notice served:	09.06.17
Name of Organisation:	Proper Burger (former Tiger Lounge), Temperance Hall, 77 Wellgate, Rotherham S60 2LZ
Type of notice served:	Prohibition
Details:	<p><u>Article 8 (1) (a)</u></p> <p>To take such general fire precautions as will ensure the safety of employees</p> <p><u>Article 8 (1) (b)</u></p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><u>Article 13 (1) (a) & 13 (2)</u></p> <p>The fire detection system is inadequate</p> <p>The fire warning system is inadequate</p> <p><u>Article 14 (2) (b)</u></p> <p>The escape routes and exits could not be used as quickly and as safely as possible</p>
Reference No:	PN.ND.526

Date of compliance of notice:	
-------------------------------	--