

Sheffield District - Public Register of Notices Served – April 2019 to March 2021

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	11 th December 2019
Name of Organisation:	Whitcroft Works, 67-69 Furnace Hill, Sheffield S3 7AH
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 11 (1) & (2) Evidence that suitable fire safety arrangements are in place was not available at the time of the visit.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/655
Date of compliance of notice:	

Date on which notice served:	12 th November 2019
Name of Organisation:	Whitcroft Works, 67-69 Furnace Hill, Sheffield S3 7AH
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 11 (1) & (2) Evidence that suitable fire safety arrangements are in place was not available at the time of the visit.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p>

	<p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/651
Date of compliance of notice:	

Date on which notice served:	24 th October 2019
Name of Organisation:	Royal Riverside Apartments, 60 Priestly Street, Sheffield S2 4DD
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 11 (1) The fire safety arrangements are not suitable and sufficient</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/648
Date of compliance of notice:	

Date on which notice served:	5 th November 2019
Name of Organisation:	Tsuki Restaurant and Bar, 58-60 West Street, Sheffield S1 4EP
Premises Type:	Restaurant with Bar
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is:</p> <p>The use of the premises for sleeping and the single means of escape into the restaurant.</p> <p>The lack of general fire precautions including unsatisfactory means of escape which makes this area unsuitable for its current use.</p>
Reference No:	PN/W/652
Date of compliance of notice:	

Date on which notice served:	26 th September 2019
Name of Organisation:	Park View Flats Complex, Fitzalan Road/St Josephs Road, Sheffield S13 9AW
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 15 Procedures for Serious and Imminent Danger and for Dangerous Areas</p>
Reference No:	EN/W/644
Date of compliance of notice:	28th November 2019

Date on which notice served:	17 th September 2019
Name of Organisation:	The Fitzgerald, 1-3 West Bar, Sheffield S3 8PQ
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/642
Date of compliance of notice:	

Date on which notice served:	19 th September 2019
Name of Organisation:	The Marples Building, Fitzalan Square, Sheffield S1 2AZ
Premises Type:	Sleeping Accommodation
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>There is insufficient fire and smoke protection between the sleeping accommodation. The situation will permit the products of fire to pass to the floors above and below. As a result insufficient fire detection and warning system, people sleeping on the Floors 1, 2, 3, 4 and 5 would be unaware of the fire and would be likely to be overcome by the products of fire before being warned of the fire or making an escape.</p> <p>Unsatisfactory means of escape from accommodation, due to combustible and ignition source stored on means of escape.</p>
Reference No:	PN/W/643
Date of compliance of notice:	20th September 2019

Date on which notice served:	22 nd August 2019
Name of Organisation:	Sang Lung, 415 Langsett Road, Sheffield S6 2LL
Premises Type:	Takeaway with Sleeping Accommodation above
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 13 (1) (a) & 13 (2) The fire fighting equipment is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p>
Reference No:	EN/W/640
Date of compliance of notice:	20th November 2019

Date on which notice served:	8 th August 2019
Name of Organisation:	The Fitzgerald, 1-3 West Bar, Sheffield S3 8PQ
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 11 (2) The fire safety arrangements have not been recorded</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/637
Date of compliance of notice:	Withdrawn – 18th September 2019

Date on which notice served:	7 th August 2019
Name of Organisation:	Prince of Wales Public House, 80 Burncross Road, Chapeltown, Sheffield S35 1SF
Premises Type:	Public House
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out</p> <p>Article 11 (2) A fire safety policy document has not been prepared</p> <p>Article 13 (3) (a) Measures for fire fighting in the premises is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The manual fire fighting equipment is inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 21 (2) (b) Safety training to employees is not repeated periodically</p>
Reference No:	EN/W/638
Date of compliance of notice:	24th October 2019

Date on which notice served:	16 th August 2019
Name of Organisation:	Sang Lung Chinese Takeaway, 415 Langsett Road, Sheffield S6 2LL
Premises Type:	Takeaway with Sleeping Accommodation above
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>The fire resisting construction between the ground floor/basement commercial areas and the means of escape route from the residential accommodation is inadequate. A fire in the commercial area would therefore make the means of escape unusable.</p> <p>There is no fire detection and warning system. People sleeping on the premises would be unaware of a fire occurring on the ground floor or basement and would be overcome by smoke and fire before being able to escape.</p>
Reference No:	PN.W.639
Date of compliance of notice:	20th November 2019

Date on which notice served:	16 th July 2019
Name of Organisation:	Coach and Horses, 13 Station Road, Chapeltown, Sheffield S35 2XE
Premises Type:	Guest House
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 10 Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p>Article 13 (1) (a) & 13 (2) The fire fighting equipment is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 21 (1) (a) Inadequate safety training is provided to employees at the time when they are first employed</p> <p>Article 21 (2) (b) Safety training to employees is not repeated periodically</p>
Reference No:	EN/W/635
Date of compliance of notice:	17th October 2019

Date on which notice served:	2 nd May 2019
Name of Organisation:	Longley Park View, 70 Longley Park, Sheffield S5 7JZ
Premises Type:	Care Home
Type of notice served:	Enforcement
Details:	<p>Article 11 (2) The fire safety arrangements have not been recorded.</p> <p>Article 17 (1) The passive fire precautions are inadequately maintained.</p>
Reference No:	EN/W/630
Date of compliance of notice:	25th June 2019

Date on which notice served:	9 th April 2019
Name of Organisation:	Chinese Table, 43 George Street, Sheffield S1 2PF
Premises Type:	Restaurant
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (a) To take such general fire precautions as will ensure the safety of employees.</p> <p>Article 11 (2) The fire safety arrangements have not been recorded.</p> <p>Article 14 (1) The escape routes were obstructed</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (c) The number, distribution and/or size of escape routes and exits is inadequate</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 14 (2) (g) The escape routes were not provided with adequate signage</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits</p> <p>Article 15 (1) (b) & 15 (3) Insufficient competent persons have been nominated to carry out evacuation procedures</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 19 (1) (a) To provide comprehensible and relevant information to employees on risks identified by the risk assessment.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/628
Date of compliance of notice:	19th June 2019