

South Yorkshire Fire and Rescue



Sheffield District - Public Register of Notices Served – April 2019 to March 2021

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	14 th January 2021
Name of Organisation:	Porterbrook 2, Pomona Street, Sheffield S11 8JG
Premises Type:	Residential Apartments
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is:</p> <p>Inadequate means of escape due to the lack of fire resisting construction between the covered carpark and the single staircase that serves the building.</p>
Reference No:	PN.W.685
Date of compliance of notice:	12th August 2021

Date on which notice served:	16 th December 2020
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 22 Where two or more Responsible Persons share, or have duties in respect of, premises each such person must co-operate with the other Responsible Person concerned so far as is necessary to enable them to comply with the requirements and prohibitions imposed on them by or under this Order</p>
Reference No:	EN.W.683
Date of compliance of notice:	28th May 2021

Date on which notice served:	21 st December 2020
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Alterations
Details:	<p>The matters which (if the changes identified below are made to the premises or the use to which they are put) may constitute a serious risk to relevant persons are:</p> <ul style="list-style-type: none"> • Inadequate smoke control • Evidence of poor compartmentation • Excessive dead end travel distances • Flammable materials present within the external wall system

	<p>You must notify this Authority:</p> <p>Before you make any changes to the layout of the premises or the fabric of the building;</p> <p>and</p> <p>Before you make any changes to the interim measures in place. Those being</p> <ul style="list-style-type: none"> • The waking watch • The wireless fire detection and alarm system <p>and</p> <p>In the event of fault or failure of the means for detecting fire and giving warning</p>
Reference No:	IN.W.684
Date withdrawn:	11th May 2023 – Superceded by IN/W/843

Date on which notice served:	11 th December 2020
Name of Organisation:	Wicker Riverside, 2-3 North Bank, Sheffield S3 8JA
Premises Type:	Purpose Built Flats
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Inadequate means of escape due to inadequate smoke control, and extended travel distance, evidence of poor compartmentation and inadequate means of fire detection and warning to support a simultaneous evacuation.</p>
Reference No:	PN.W.682
Date of withdrawal of notice:	19th December 2020 – superceded by IN.W.684

Date on which notice served:	3 rd November 2020
Name of Organisation:	OYO The Sheffield Metropolitan, Blonk Street, Sheffield S1 2AU
Premises Type:	Hotel
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (a) and (1) (b) To take such general fire precautions as will ensure the safety of employees and the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 13 (3) (c) Necessary contacts with external emergency services have not been arranged.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p>

	<p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Article 17 (1) The structural and passive fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 22 Where two or more Responsible Persons share, or have duties in respect of, premises each such person must co-operate with the other Responsible Person concerned so far as is necessary to enable them to comply with the requirements and prohibitions imposed on them by or under this Order.</p>
Reference No:	EN/W/681
Date of compliance of notice:	

Date on which notice served:	16 th October 2020
Name of Organisation:	146/146a London Road, Sheffield S2 4LT
Premises Type:	Restaurant and Takeaway
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is</p> <p>Inadequate means of detection and warning of fire throughout the premises.</p> <p>This situation would permit a fire to go undetected to any sleeping occupants of the premises.</p> <p>Inadequate means of protection of escape routes due to lack of fire protection and high risk items and combustibles stored on the means of escape.</p> <p>This situation would permit the products of fire and smoke to pass throughout the premises before residents can be safely evacuated.</p>
Reference No:	PN/W/679
Date of compliance of notice:	25th March 2022

Date on which notice served:	22 nd September 2020
Name of Organisation:	2 Ways 2 Tan, 50 High Street, Mosborough, Sheffield S20 5AE
Premises Type:	Beauty Salon and Retail Premises
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (a) To take such general fire precautions as will ensure the safety of employees.</p> <p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 11 (1) The fire safety arrangements are not suitable and sufficient</p>

	<p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 13 (1) (a) & 13 (2) The firefighting equipment is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 14 (2) (g) The escape routes were not provided with adequate signage</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p>Article 19 (1) (c) To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises</p>
Reference No:	EN/W/678
Date of compliance of notice:	7th December 2020

Date on which notice served:	7 th September 2020
Name of Organisation:	Royal Riverside Apartments, 6 Priestley Street, Sheffield S2 4DD
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 11 (1) The fire safety arrangements are not suitable and sufficient</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The automatic opening vents are inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/674
Date of compliance of notice:	9th November 2020

Date on which notice served:	18 th September 2020
Name of Organisation:	2 Ways 2 Tan, 50 High Street, Mosborough, Sheffield S20 5AE
Premises Type:	Beauty Salon and Retail Premises
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Inadequate means of detection and warning and inadequate protection to escape routes. Lack of compartmentation between basement and ground floor. Inadequate means for fighting fire.</p>
Reference No:	PN/W/677
Date of compliance of notice:	7th December 2020

Date on which notice served:	4 th September 2020
Name of Organisation:	Apollo Taxis. Unit 3, 150 Worksop Road, Sheffield S9 3TN
Premises Type:	Garage with First Floor Offices
Type of notice served:	Alterations
Details:	<p>The matters which constitute a serious risk to relevant persons are:</p> <ul style="list-style-type: none"> • any use of the ground floor as a workspace or storage, as this area forms part of the means of escape for the occupants of the first floor. <p><u>Change(s) referred to above which may constitute a risk</u></p> <p>You must notify this Authority before you:</p> <p>use the ground floor as a workspace; and / or</p> <p>use the ground floor for storage; and / or</p> <p>use the ground floor for any purpose other than for the means of access or escape for occupants of the first floor office;</p>
Reference No:	IN/W/675
Date Withdrawn:	

Date on which notice served:	6 th August 2020
Name of Organisation:	The Glen Private Nursing Home, 224 Abbeydale Road South, Sheffield S17 3LA
Premises Type:	Nursing Home
Type of notice served:	Enforcement
Details:	Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.
Reference No:	EN/W/671
Date of compliance of notice:	21st August 2020

Date on which notice served:	6 th February 2020
Name of Organisation:	Whitcroft Works, 67-69 Furnace Hill, Sheffield S3 7AH
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible
Reference No:	EN/W/661
Date Notice Withdrawn:	20th November 2020

Date on which notice served:	21 st January 2020
Name of Organisation:	St James House, Vicar Lane, Sheffield S1 2EX
Premises Type:	Office
Type of notice served:	Enforcement
Details:	Article 8 (1) (a) To take such general fire precautions as will ensure the safety of employees and those who are not their employees. Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.
Reference No:	EN/W/659
Date Notice Withdrawn:	23rd February 2021

Date on which notice served:	10 th January 2020
Name of Organisation:	The Cumberland, 35 High Street, Beighton, Sheffield S20 1EE
Premises Type:	Public House
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 10 Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p>Article 14 (2) (a) The escape routes did not lead, as directly as possible, to a place of safety</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p>Article 17 (1) The manual firefighting equipment is inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 21 (1) (a) Inadequate safety training is provided to employees at the time when they are first employed</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises</p> <p>Article 22 (1) (a) Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005</p> <p>Article 22 (1) (c) Failure to inform other responsible persons sharing the same premises of the risks arising out of, or in connection with, your undertaking</p>
Reference No:	EN/W/656
Date of compliance of notice:	19 th March 2020

Date on which notice served:	20 th January 2020
Name of Organisation:	Apollo Taxis, Unit 3, 150 Worksop Road, Sheffield S9 3TN
Premises Type:	Garage with First Floor Offices
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>Unsatisfactory means of escape, unsatisfactory means of detection and warning and extended travel distances from the first floor offices.</p>
Reference No:	PN/W/658
Date of compliance of notice:	1st June 2020

Date on which notice served:	11 th December 2019
Name of Organisation:	Whitcroft Works, 67-69 Furnace Hill, Sheffield S3 7AH
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 11 (1) & (2) Evidence that suitable fire safety arrangements are in place was not available at the time of the visit.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/655
Date Notice Withdrawn:	20th November 2020

Date on which notice served:	12 th November 2019
Name of Organisation:	Whitcroft Works, 67-69 Furnace Hill, Sheffield S3 7AH
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient.</p> <p>Article 11 (1) & (2) Evidence that suitable fire safety arrangements are in place was not available at the time of the visit.</p> <p>Article 13 (1) (a) & 13 (2) The fire detection system is inadequate.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/651
Date of compliance of notice:	6th February 2020

Date on which notice served:	24 th October 2019
Name of Organisation:	Royal Riverside Apartments, 60 Priestly Street, Sheffield S2 4DD
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 11 (1) The fire safety arrangements are not suitable and sufficient</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 15 (1) (a) Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p>

	Article 17 (1) The emergency lighting is inadequately maintained
Reference No:	EN/W/648
Date of compliance of notice:	7th September 2020 - superceded by EN/W/674

Date on which notice served:	5 th November 2019
Name of Organisation:	Tsuki Restaurant and Bar, 58-60 West Street, Sheffield S1 4EP
Premises Type:	Restaurant with Bar
Type of notice served:	Restriction
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk is:</p> <p>The use of the premises for sleeping and the single means of escape into the restaurant.</p> <p>The lack of general fire precautions including unsatisfactory means of escape which makes this area unsuitable for its current use.</p>
Reference No:	PN/W/652
Date of compliance of notice:	6th February 2020

Date on which notice served:	26 th September 2019
Name of Organisation:	Park View Flats Complex, Fitzalan Road/St Josephs Road, Sheffield S13 9AW
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 15 Procedures for Serious and Imminent Danger and for Dangerous Areas</p>
Reference No:	EN/W/644
Date of compliance of notice:	28th November 2019

Date on which notice served:	17 th September 2019
Name of Organisation:	The Fitzgerald, 1-3 West Bar, Sheffield S3 8PQ
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible.</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/642
Date of compliance of notice:	21st May 2020

Date on which notice served:	19 th September 2019
Name of Organisation:	The Marples Building, Fitzalan Square, Sheffield S1 2AZ
Premises Type:	Sleeping Accommodation
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>There is insufficient fire and smoke protection between the sleeping accommodation. The situation will permit the products of fire to pass to the floors above and below. As a result insufficient fire detection and warning system, people sleeping on the Floors 1, 2, 3, 4 and 5 would be unaware of the fire and would be likely to be overcome by the products of fire before being warned of the fire or making an escape.</p> <p>Unsatisfactory means of escape from accommodation, due to combustible and ignition source stored on means of escape.</p>
Reference No:	PN/W/643
Date of compliance of notice:	20th September 2019

Date on which notice served:	22 nd August 2019
Name of Organisation:	Sang Lung, 415 Langsett Road, Sheffield S6 2LL
Premises Type:	Takeaway with Sleeping Accommodation above
Type of notice served:	Enforcement
Details:	<p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 13 (1) (a) & 13 (2) The fire fighting equipment is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p>
Reference No:	EN/W/640
Date of compliance of notice:	20th November 2019

Date on which notice served:	8 th August 2019
Name of Organisation:	The Fitzgerald, 1-3 West Bar, Sheffield S3 8PQ
Premises Type:	Purpose Built Flats
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1) The Fire Safety Risk Assessment was not suitable and sufficient</p> <p>Article 11 (2) The fire safety arrangements have not been recorded</p> <p>Article 13 (1) (a) & 13 (2) The fire warning system is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p>
Reference No:	EN/W/637
Date of compliance of notice:	Withdrawn – 18th September 2019

Date on which notice served:	7 th August 2019
Name of Organisation:	Prince of Wales Public House, 80 Burncross Road, Chapeltown, Sheffield S35 1SF
Premises Type:	Public House
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1) A Fire Safety Risk Assessment has not been carried out</p> <p>Article 11 (2) A fire safety policy document has not been prepared</p> <p>Article 13 (3) (a) Measures for fire fighting in the premises is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1) The manual fire fighting equipment is inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 21 (2) (b) Safety training to employees is not repeated periodically</p>
Reference No:	EN/W/638
Date of compliance of notice:	24th October 2019

Date on which notice served:	16 th August 2019
Name of Organisation:	Sang Lung Chinese Takeaway, 415 Langsett Road, Sheffield S6 2LL
Premises Type:	Takeaway with Sleeping Accommodation above
Type of notice served:	Prohibition
Details:	<p>The Fire and Rescue Authority are further of the opinion that the matter(s) which give rise to the said risk are:</p> <p>The fire resisting construction between the ground floor/basement commercial areas and the means of escape route from the residential accommodation is inadequate. A fire in the commercial area would therefore make the means of escape unusable.</p> <p>There is no fire detection and warning system. People sleeping on the premises would be unaware of a fire occurring on the ground floor or basement and would be overcome by smoke and fire before being able to escape.</p>
Reference No:	PN.W.639
Date of compliance of notice:	20th November 2019

Date on which notice served:	16 th July 2019
Name of Organisation:	Coach and Horses, 13 Station Road, Chapeltown, Sheffield S35 2XE
Premises Type:	Guest House
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b) To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 10 Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p>Article 13 (1) (a) & 13 (2) The fire fighting equipment is inadequate</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 21 (1) (a) Inadequate safety training is provided to employees at the time when they are first employed</p> <p>Article 21 (2) (b) Safety training to employees is not repeated periodically</p>
Reference No:	EN/W/635
Date of compliance of notice:	17th October 2019

Date on which notice served:	2 nd May 2019
Name of Organisation:	Longley Park View, 70 Longley Park, Sheffield S5 7JZ
Premises Type:	Care Home
Type of notice served:	Enforcement
Details:	<p>Article 11 (2) The fire safety arrangements have not been recorded.</p> <p>Article 17 (1) The passive fire precautions are inadequately maintained.</p>
Reference No:	EN/W/630
Date of compliance of notice:	25th June 2019

Date on which notice served:	9 th April 2019
Name of Organisation:	Chinese Table, 43 George Street, Sheffield S1 2PF
Premises Type:	Restaurant
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (a) To take such general fire precautions as will ensure the safety of employees.</p> <p>Article 11 (2) The fire safety arrangements have not been recorded.</p> <p>Article 14 (1) The escape routes were obstructed</p> <p>Article 14 (2) (b) The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 14 (2) (c) The number, distribution and/or size of escape routes and exits is inadequate</p> <p>Article 14 (2) (f) Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 14 (2) (g) The escape routes were not provided with adequate signage</p> <p>Article 14 (2) (h) The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits</p> <p>Article 15 (1) (b) & 15 (3) Insufficient competent persons have been nominated to carry out evacuation procedures</p> <p>Article 17 (1) The structural fire precautions are inadequately maintained.</p> <p>Article 17 (1) The fire alarm system is inadequately maintained</p> <p>Article 17 (1) The emergency lighting is inadequately maintained</p> <p>Article 19 (1) (a) To provide comprehensible and relevant information to employees on risks identified by the risk assessment.</p> <p>Article 21 (2) (a) Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/628
Date of compliance of notice:	19th June 2019