

# South Yorkshire Fire and Rescue



## Sheffield District - Public Register of Notices Served – April 2017 to March 2019

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	7 <sup>th</sup> April 2017
Name of Organisation:	Sheffield Gauge Plate Ltd, Bastock Road, Sheffield S6 2AE
Premises Type:	Factory (R)
Type of notice served:	Enforcement
Details:	<p><b>Article 9 (1)</b> - A Fire Safety Risk Assessment has not been carried out.</p> <p><b>Article 12 (4) (a)</b> - Arrangements for the safe handling and/or storage and/or transport of dangerous substances and/or waste containing dangerous substances is inadequate.</p> <p><b>Article 13 (1) (a) &amp; 13 (2)</b> - The fire warning system is inadequate.</p> <p><b>Article 14 (1)</b> - The escape routes were obstructed.</p> <p><b>Article 14 (2) (b)</b> - The escape routes and exits could not be used as quickly and as safely as possible.</p> <p><b>Article 14 (2) (f)</b> - Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p><b>Article 14 (2) (h)</b> - The escape routes did not have adequate emergency lighting in case of failure of normal lighting circuits.</p> <p><b>Article 17 (1)</b> - The manual fire fighting equipment is inadequately maintained.</p> <p><b>Article 21 (2) (a)</b> - Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No:	EN/W/520
Date of compliance of notice:	

