

Rotherham District - Public Register of Notices Served – April 2009 to March 2011

Date on which notice served:	31/03/2011
Name of Organisation:	Montrose Furnishings, 42-44 Westgate, Rotherham S60 1AS
Type of notice served:	Prohibition
Details:	<p>The fire warning system is inadequate.</p> <p>The escape routes were obstructed.</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside.</p> <p>The escape routes were not provided with adequate signage.</p> <p>The escape routes were not adequately lit.</p> <p>The structural fire precautions are inadequately maintained.</p>
Reference No	PN/ND.126
Date of compliance of notice:	28/09/2011

Date on which notice served:	25/01/2011
Name of Organisation:	Farm Foods, 2-4 Howard Street, Rotherham, S60 1QY
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>A Fire Safety Risk Assessment was not available at the time of inspection.</p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>A fire safety policy document was not available at the time of the visit.</p> <p>The external escape routes from the adjacent Poundland premises were found to be obstructed by Farm Foods stock.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>There was inadequate information regarding employees provided to a competent appointed person to allow them to fulfil their function for the purposes of assisting with preventive and protective measures.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/ND/116
Date of compliance of notice:	28/03/2011

Date on which notice served:	25/02/10
Name of Organisation:	Dinnington Primary School, School Street, Dinnington, Sheffield, S25 2PE
Type of notice served:	Enforcement
Details:	<p>The escape routes were obstructed.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p>
Reference No	EN.ND.23
Date of compliance of notice:	25/03/2010

Date on which notice served:	20/11/2009
Name of Organisation:	Amigos, 57 Wellgate, Rotherham, S60 2LT
Type of notice served:	Enforcement
Details:	<p>Means of giving Warning in Case of Fire.</p> <p>Means for Securing the Means of Escape.</p> <p>Means of Escape.</p> <p>Means for fighting fire (by persons in the building)</p> <p>Providing a suitable and sufficient fire risk assessment.</p> <p>Formulate a written fire evacuation plan.</p> <p>Staff should receive training in the use of fire extinguishers.</p> <p>All small portable electrical appliances must by P.A.T. tested annually.</p> <p>The building must have a five yearly fixed wiring test carried out by a competent electrician and a certificate of conformity produced.</p> <p>A gas certificate must be produced for all gas appliances.</p>
Reference No	EN.ND.22
Date of compliance of notice:	11/01/2010

Date on which notice served:	02/10/2009
Name of Organisation:	Cliffe Field House, 48 Station Street, Swinton, Rotherham, S64 8LU
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees and of persons who are not his employees.</p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.</p> <p>A fire safety policy document was not available at the time of the visit.</p> <p>The fire detection system is inadequate.</p> <p>Insufficient competent persons have been nominated to implement fire fighting measures.</p> <p>The escape routes were not adequately lit.</p> <p>Insufficient competent persons have been nominated to carry out evacuation procedures.</p> <p>Insufficient information was made available to persons in the event of serious and/or imminent danger.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN.ND.21
Date of compliance of notice:	30/10/2009

Date on which notice served:	23/09/2009
Name of Organisation:	B & M Stores, 23-25 College Street, Rotherham, S65 1AG
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees.</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>A fire safety policy document has not been prepared.</p> <p>Measures for fire fighting in the premises are inadequate.</p> <p>The escape routes were not provided with adequate signage.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The fire alarm system is inadequately maintained.</p> <p>To provide comprehensible and relevant information to employees on</p>

	<p>appropriate procedures and drills to be followed in the event of serious and imminent danger.</p> <p>To provide comprehensible and relevant information to employees on persons nominated for fire fighting on the premises and/or assist in evacuation procedures from the premises.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN.ND.20
Date of compliance of notice:	30/10/2009

Date on which notice served:	14/04/2009
Name of Organisation:	Red Lion, High Street, Watch upon Dearne, Rotherham, S73 7QG
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of employees.</p> <p>A Fire Safety Risk Assessment was not available at the time of the inspection.</p> <p>The fire detection system is inadequate.</p> <p>The fire fighting equipment is inadequate.</p> <p>The structural fire precautions are inadequately maintained.</p>
Reference No	EN.ND.19
Date of compliance of notice:	04/06/2009