

Doncaster District - Public Register of Notices Serviced – April 2011 to March 2013

Date on which notice served:	19/03/2013
Name of Organisation:	Fortune Cantonese Restaurant, Manor Road, Hatfield, Doncaster
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. The Fire Safety Risk Assessment was not suitable and sufficient. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. The escape routes were obstructed. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The structural and passive fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises. Safety training to employees is not repeated periodically.
Reference No	EN.E,303
Date of compliance of notice:	16/05/2013

Date on which notice served:	23/11/2012
Name of Organisation:	The Crown Hotel, High Street, Askern, Doncaster DN6 0AB
Type of notice served:	Prohibition
Details:	Inadequate means of escape from second floor and inadequate means of giving warning in the event of fire.
Reference No	PN.E.279
Date of compliance of notice:	09/02/2016 Withdrawn

Date on which notice served:	23/11/2012
Name of Organisation:	The Crown Hotel, High Street, Askern, Doncaster DN6 0AB
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequate. The fire warning system is inadequate. The manual fire fighting equipment is inadequately maintained.
Reference No	EN.E.278
Date of compliance of notice:	06/02/2013

Date on which notice served:	07/11/2012
Name of Organisation:	Liberty Bar & Grill, 7 Cleveland Street, Doncaster, DN1 3EH
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient Inadequate safety training is provided to employees at the time when they are first employed The fire alarm system is inadequately maintained The emergency lighting is inadequately maintained The escape routes were obstructed Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005

Reference No	EN.E.275
Date of compliance of notice:	09/01/2013

Date on which notice served:	05/10/2012
Name of Organisation:	White Hart, Market Place, Thorne, Doncaster, DN8 5DG
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/271
Date of compliance of notice:	07/12/2012

Date on which notice served:	02/10/2012
Name of Organisation:	Queen Elizabeth Court, Queen Street, Thorne, Doncaster, DN8 5AL
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The escape routes and exits could not be used as quickly and as safely as possible. The escape routes were not provided with adequate signage. The structural fire precautions are inadequately maintained.
Reference No	EN/273
Date of compliance of notice:	22/05/2013

Date on which notice served:	13/08/2012
Name of Organisation:	The Redeemed Christian Church of God – Kingdom Life Assembly, Shotton Walk, Doncaster, DN1 3RH
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. A Fire Safety Risk Assessment has not been carried out. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. A fire safety policy document was not available at the time of the visit. The fire detection system is inadequate. The fire warning system is inadequate. The fire fighting equipment is inadequate. The escape routes were obstructed. The escape routes did not lead, as directly as possible, to a place of safety. The escape routes and exits could not be used as quickly and as safely as possible. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not provided with adequate signage.

	<p>The escape routes were not adequately lit.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>Insufficient competent persons have been nominated to carry out evacuation procedures.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>To provide comprehensible and relevant information to employees on risks identified by the risk assessment.</p> <p>To provide comprehensible and relevant information to employees on preventative and protective measures.</p> <p>To provide comprehensible and relevant information to employees on appropriate procedures and drills to be followed in the event of serious and imminent danger.</p> <p>Inadequate safety training is provided to employees at the time when they are first employed.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Safety training to employees is not repeated periodically.</p>
Reference No	EN/265
Date of compliance of notice:	18/04/2013

Date on which notice served:	01/08/2012
Name of Organisation:	The Redeemed Christian Church of God, Shotton Walk, Hyde Park, Doncaster DN1 3RH
Type of notice served:	Prohibition
Details:	Inadequate protection to means of escape routes and inadequate means of giving warning in the event of fire from persons sleeping in the premises.
Reference No	PN.E.262
Date of compliance of notice:	03/08/2012

Date on which notice served:	26/07/2012
Name of Organisation:	The Poacher, Radburn Road, New Rossington, Doncaster DN11 0SH
Type of notice served:	Enforcement
Details:	<p>A Fire Safety Risk Assessment has not been carried out.</p> <p>The fire alarm system is inadequately maintained.</p> <p>The emergency lighting is inadequately maintained.</p> <p>The manual fire fighting equipment is inadequately maintained.</p> <p>The structural fire precautions are inadequately maintained.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place.</p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>The fire detection system is inadequate.</p>
Reference No	EN.257
Date of compliance of notice:	30/08/2012

Date on which notice served:	25/07/2012
Name of Organisation:	Doncaster Tandoori Restaurant, 19-21 Copley Road, Doncaster DN1 2PE
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment was not available at the time of the inspection. A fire detection system is inadequate. The escape routes were not provided with adequate signage. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN.E.258
Date of compliance of notice:	25/10/2012

Date on which notice served:	24/07/2012
Name of Organisation:	The Crown Hotel, High Street, Askern, Doncaster, DN6 0AB
Type of notice served:	Prohibition
Details:	Inadequate means of escape from second floor and inadequate means of giving warning in the event of fire.
Reference No	PN.E.255
Date of compliance of notice:	23/11/2012 Withdrawn

Date on which notice served:	23/07/2012
Name of Organisation:	The Crown Hotel, High Street, Askern, Doncaster, DN6 0AB
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequate. The fire warning system is inadequate. The manual fire fighting equipment is inadequately maintained.
Reference No	EN.256
Date of compliance of notice:	23/11/2012 Withdrawn

Date on which notice served:	16/04/2012
Name of Organisation:	E M Mellor, 17 Highfield Road, Wheatley, Doncaster DN1 2LA
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. Sliding/revolving doors must not be used for emergency exits. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. Inadequate safety training is provided to employees at the time when they are fire employed.
Reference No	EN.E.220
Date of compliance of notice:	01/08/2012

Date on which notice served:	04/04/2012
Name of Organisation:	The White Swan, Balby Road, Balby, Doncaster DN4 0NE
Type of notice served:	Prohibition
Details:	Inadequate means of warning in the event of fire

Reference No	PN.E.216
Date of compliance of notice:	09.08.16

Date on which notice served:	21/03/2012
Name of Organisation:	Sadiqa, 5-7 King Street, Thorne, Doncaster, DN8 5BD
Type of notice served:	Prohibition
Details:	Inadequate detection and warning in case of fire. Inadequate means of escape in case of fire.
Reference No	PN.212
Date of compliance of notice:	22.10.18

Date on which notice served:	24/02/2012
Name of Organisation:	The White Swan, Balby Road, Balby, Doncaster DN4 0NE
Type of notice served:	Prohibition
Details:	The fire detection system is inadequate. The escape routes are inadequate from the first floor.
Reference No	PN.E.205
Date of compliance of notice:	04/04/2012

Date on which notice served:	24/02/2012
Name of Organisation:	The White Swan, Balby Road, Balby, Doncaster DN4 0NE
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The escape routes were obstructed. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN.E.204
Date of compliance of notice:	19/04/2012

Date on which notice served:	11/01/2012
Name of Organisation:	Carcroft Primary School, Owston Road, Carcroft, Doncaster, DN6 8DR
Type of notice served:	Prohibition
Details:	The number, distribution and/or size of escape routes and exits is inadequate. Emergency doors do not open in the direction of escape.
Reference No	PN.E.187
Date of compliance of notice:	14/03/2012

Date on which notice served:	21/11/2011
Name of Organisation:	Victoria Lodge, 138 Thorne Road, Edenthorpe, Doncaster, DN3 2LU
Type of notice served:	Enforcement
Details:	The structural fire precautions are inadequately maintained, fire resisting doors not working correctly. The escape routes and exits could not be used as quickly and as safely as possible. Fire exits and doors on escape routes could not be easily and immediately opened from the inside.

Reference No	EN.E.171
Date of compliance of notice:	30/01/2012

Date on which notice served:	16/11/2011
Name of Organisation:	Ernelsthorpe Manor and Lodge, Cow House Lane, Armthorpe, Doncaster DN3 3EE
Type of notice served:	Enforcement
Details:	The structural fire precautions are inadequately maintained, fire resisting doors not working correctly. The escape routes and exits could not be used as quickly and as safely as possible.
Reference No	EN.E.170
Date of compliance of notice:	30/01/2012

Date on which notice served:	19/10/2011
Name of Organisation:	Kingsway House, Hall Gate, Doncaster, DN1 3NX
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and those who are not their employees. To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire Safety Risk Assessment has not been carried out. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005. A fire safety policy document has not been prepared. The fire detection system is inadequate. The escape routes were obstructed. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. To provide comprehensible and relevant information to employees on risks identified by the risk assessment. Inadequate safety training is provided to employees at the time when they are first employed.
Reference No	EN.E.167
Date of compliance of notice:	14/12/2011

Date on which notice served:	07/10/2011
Name of Organisation:	Vintage Rock Bar, 1 St George Gate, Doncaster, DN1 1LE
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The fire detection and fire warning system is inadequate. The escape routes were obstructed. The escape routes and exits could not be used as quickly and as safely as possible. The structural fire precautions are inadequately maintained. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate safety training is provided to employees at the time when

	they are first employed. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises. Safety training to employees is not repeated periodically.
Reference No	EN.E.163
Date of compliance of notice:	12/12/2011

Date on which notice served:	09/09/2011
Name of Organisation:	Niaz Mini Market, 47 Kings Road, Doncaster, DN1 2NA
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The fire warning system is inadequate. The structural fire precautions are inadequately maintained.
Reference No	EN.E.151
Date of compliance of notice:	26/10/2011

Date on which notice served:	31/08/2011
Name of Organisation:	Eastfield Hall/Lodge, Moss Road, Askern, Doncaster, DN6 0JZ
Type of notice served:	Enforcement
Details:	The structural fire precautions are inadequately maintained.
Reference No	EN.E.145
Date of compliance of notice:	03/10/2011

Date on which notice served:	12/08/2011
Name of Organisation:	Thorne Carpets, King Street, Thorne, Doncaster
Type of notice served:	Enforcement
Details:	The escape routes were inadequate
Reference No	EN.E.140
Date of compliance of notice:	05/10/2011

Date on which notice served:	24/06/2011
Name of Organisation:	Bay Horse Hotel, Chapel Street, Bentley, Doncaster, DN5 0DE
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequately maintained. The fire warning system is inadequately maintained. The emergency lighting is inadequately maintained. The fire alarm system is inadequately maintained.
Reference No	EN.E.135
Date of compliance of notice:	04/08/2011