

Rotherham District - Public Register of Notices Served – April 2008 to March 2009

Date on which notice served:	13/06/2008
Name of Organisation:	Intercity UK Ltd, Sandbeck Way, Hellaby Industrial Estate, Hellaby, Rotherham, S66 8QL
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees.
Reference No	EN.ND.18
Date of compliance of notice:	02/09/2008

Date on which notice served:	27/05/2008
Name of Organisation:	Allott Bros and Leigh Ltd, Fullerton Road, The Ickles, Rotherham, S60 1DJ
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees. The fire warning system is inadequate. The fire fighting equipment is not easily accessible. The escape routes and exits could not be used as quickly and as safely as possible. The escape routes were not provided with adequate signage. The escape routes were not adequately lit. Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises. Safety training to employees is not repeated periodically.
Reference No	EN.ND.17
Date of compliance of notice:	29/08/2008

Date on which notice served:	09/05/2008
Name of Organisation:	House in Multiple Occupation (HIMO), 16 Hardwicke Road, Eastwood, Rotherham, S65 1RE
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The fire fighting equipment is inadequate. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not adequately lit.
Reference No	EN.ND.16
Date of compliance of notice:	26.03/2009

Date on which notice served:	09/05/2008
Name of Organisation:	House in Multiple Occupation (HIMO), 29 Myrtle Crescent, Wickersley, Rotherham, S66 2PD
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The fire fighting equipment is inadequate. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not adequately lit.
Reference No	EN.ND.15
Date of compliance of notice:	07/08/2008

Date on which notice served:	08/05/2008
Name of Organisation:	House in Multiple Occupation (HIMO), 27 Tooker Road, Rotherham, S60 2PS
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire safety Risk Assessment has not been carried out. The fire detection system is inadequate. The fire fighting equipment is inadequate. The escape routes were not adequately lit. Fire exits and doors on escape routes could not be easily and immediately opened from the inside.
Reference No	EN.ND.14
Date of compliance of notice:	26/03/2009

Date on which notice served:	09/05/2008
Name of Organisation:	House in Multiple Occupation (HIMO), 12 Whybourne Grove, Rotherham, S60 2LQ
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire Safety Risk Assessment has not been carried out. The fire detection system is inadequate. The fire fighting equipment is inadequate. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The escape routes were not adequately lit.
Reference No	EN.ND.13
Date of compliance of notice:	26/03/2009