

Barnsley District - Public Register of Notices Served – April 2009 to March 2011

Date on which notice served:	16/03/2011
Name of Organisation:	18-18a Market Street, Penistone, Sheffield S36 6BZ
Type of notice served:	Enforcement
Details:	The structural fire precautions are inadequately maintained. Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005. Fail, without reasonable excuse to comply with any requirements under Article 27 (1) (c) or (d).
Reference No	EN.NA.120
Date of compliance of notice:	10/05/2011

Date on which notice served:	24/01/2011
Name of Organisation:	Barnsley Conservative Club, 36 Pitt Street, Barnsley S70 1AW
Type of notice served:	Enforcement
Details:	A Fire Safety Risk Assessment has not been carried out. The manual fire fighting equipment is inadequately maintained. The emergency lighting is inadequately maintained. Inadequate co-operation with other responsible persons sharing the same premises to comply with the requirements and prohibitions imposed under the Regulatory Reform (Fire Safety) Order 2005.
Reference No	EN.NA.114
Date of compliance of notice:	04/04/2011

Date on which notice served:	10/01/2011
Name of Organisation:	The Britannia, 85 Sheffield Road, Penistone, Sheffield S36 6HH
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of persons who are not his employees. A Fire Safety Risk Assessment has not been carried out. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN/NA/110
Date of compliance of notice:	2303/2011

Date on which notice served:	17/08/2010
Name of Organisation:	Athersley Social Working Mens Club, 6 Mansfield Road, Athersley North, Barnsley S71 3AR
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment has not been reviewed on a regular basis. The escape routes were not adequately lit. The manual fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Safety training to employees is not repeated periodically.
Reference No	EN99
Date of compliance of notice:	07/10/2010

Date on which notice served:	11/08/2010
Name of Organisation:	Forest Dale Hotels, Ardsley House Hotel, Doncaster Road, Barnsley, S71 5EH
Type of notice served:	Enforcement
Details:	The fire detection system is inadequate
Reference No	EN.NA.98
Date of compliance of notice:	16/12/2010

Date on which notice served:	08/06/2010
Name of Organisation:	Rosehill Residential Home, Rosehill Cottage, Keresforth Road, Dodworth, Barnsley S75 3EB
Type of notice served:	Enforcement
Details:	The Fire Safety Risk –Assessment has not been reviewed on a regular basis. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. The structural fire precautions are inadequately maintained. Safety training to employees is not repeated periodically.
Reference No	EN.NA.05.10/11
Date of compliance of notice:	12/08/2010

Date on which notice served:	02/06/2010
Name of Organisation:	Simply Furnishings, 1a Cheapside, Metropolitan Centre, Barnsley S70 1RA
Type of notice served:	Enforcement
Details:	The Fire Safety Risk Assessment has not been reviewed on a regular basis. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The manual fire fighting equipment is inadequately maintained. The automatic fire fighting equipment is inadequately maintained. The fire alarm system is inadequately maintained. The emergency lighting is inadequately maintained. Safety training to employees is not repeated periodically.
Reference No	EN.NA.04.10/11
Date of compliance of notice:	17/08/2010

Date on which notice served:	13/05/2010
Name of Organisation:	Quit Charity Shop, 2-4 May Day Green, Barnsley, S70 1SH
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees. The Fire Safety Risk Assessment was not suitable and sufficient. The fire detection system is inadequate. The escape routes were obstructed. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained.

Reference No	EN.NA.03.10/11
Date of compliance of notice:	20/05/2010

Date on which notice served:	07/05/2010
Name of Organisation:	Quit Charity Shop, 2-4 May Day Green, Barnsley, S70 1SH
Type of notice served:	Prohibition
Details:	The fire detections system is inadequate. The escape routes were obstructed. The structural fire precautions are inadequately maintained. Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005.
Reference No	PN.NA.01.10/11
Date of compliance of notice:	20/05/10

Date on which notice served:	16/04/2010
Name of Organisation:	Gallery Menswear, 18 Market Hill, Barnsley, S70 2QE
Type of notice served:	Enforcement
Details:	The existing fire alarm system should be inspected by a competent electrical engineer and an inspection and Servicing certificate as detailed in Annex G of British Standard 5839: Part 1: 2002 or an equivalent standard should be forwarded to this department.
Reference No	EN.NA.02.10/11
Date of compliance of notice:	18/06/2010

Date on which notice served:	12/04/2010
Name of Organisation:	The Three Horseshoes, Barnsley Road, Brierley, Barnsley, S72 9JT
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees. A Fire Safety Risk Assessment has not been carried out. The fire warning system is inadequately maintained. The emergency lighting is inadequately maintained.
Reference No	EN.NA.04.09/10
Date of compliance of notice:	04/06/2010

Date on which notice served:	20/01/2010
Name of Organisation:	The Citrus Rooms, 6 Eastgate, Barnsley, S70 2EX
Type of notice served:	Enforcement
Details:	To take such general fire precautions as will ensure the safety of employees and non employee's. The Fire Safety Risk Assessment was not suitable and sufficient. Fire exits and doors on escape routes could not be easily and immediately opened from the inside. The structural fire precautions are inadequately maintained. The fire alarm system is inadequately maintained. Inadequate safety training is provided to employees at the time when they are first employed. Safety training to employees is not repeated periodically.
Reference No	EN.NA.03.09/10
Date of compliance of notice:	Notice Withdrawn 05/10/2012

Date on which notice served:	18/12/2009
Name of Organisation:	Lucorum, Hanson Street, Barnsley, S27 2HZ
Type of notice served:	Enforcement
Details:	<p>To take such general fire precautions as will ensure the safety of persons who are not his employees.</p> <p>The Fire Safety Risk Assessment has not been reviewed on a regular basis.</p> <p>The escape routes were obstructed.</p> <p>The emergency lighting is inadequately maintained.</p> <p>Inadequate safety training is provided to enable the employees to safeguard themselves and other persons on the premises.</p>
Reference No	EN/NA.02.09/10
Date of compliance of notice:	12/01/2010

Date on which notice served:	08/06/2009
Name of Organisation:	Darfield Club, Upperwood Road, Darfield, Barnsley, S73 9QR
Type of notice served:	Enforcement
Details:	The premises are not provided with a fire alarm system.
Reference No	EN/NA.01.09/10
Date of compliance of notice:	07/07/2009