

South Yorkshire Fire and Rescue

Barnsley District - Public Register of Notices Served – April 2017 to March 2019

The Enforcement Register – This register details Enforcement, Prohibition and Alteration Notices that have been served on business premises under the [Regulatory Reform \(Fire Safety\) Order 2005](#).

Date on which notice served:	16.01.19
Name of Organisation:	Autumn House, Nursing Home, 2 Station Road, Worsbrough Dale, Barnsley, S70 4SY.
Type of notice served:	Enforcement
Details:	<p><u>Article 9 (1)</u> The Fire Safety Risk Assessment was not suitable and sufficient</p> <p><u>Article 11 (1)</u> The fire safety arrangements are not suitable and sufficient</p> <p><u>Article 13 (1) (a) & 13 (2)</u> The fire warning system is inadequate</p> <p><u>Article 13 (3) (a)</u> Measures for fire fighting in the premises is inadequate</p> <p><u>Article 14 (2) (b)</u> The escape routes and exits could not be used as quickly and as safely as possible</p> <p><u>Article 15 (1) (a)</u> Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p><u>Article 17 (1)</u> The fire alarm system is inadequately maintained</p> <p><u>Article 17 (1)</u> The emergency lighting is inadequately maintained</p>
Reference No:	PN.NA.619

Date of compliance of notice:	
-------------------------------	--

Date on which notice served:	12.10.18
Name of Organisation:	Carr House, (1-12), Doncaster Road, Goldthorpe, Barnsley, South Yorkshire, S63 9HL.
Type of notice served:	Enforcement
Details:	<p><u>Article 8 (1) (b)</u></p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p><u>Article 9 (1)</u></p> <p>A Fire Safety Risk Assessment has not been carried out</p> <p><u>Article 10</u></p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p><u>Article 11 (1) & (2)</u></p> <p>A fire safety policy document has not been prepared</p> <p><u>Article 14 (2) (b)</u></p> <p>The escape routes and exits could not be used as quickly and as safely as possible</p> <p><u>Article 17 (1)</u></p> <p>The structural fire precautions are inadequately maintained</p> <p><u>Article 17 (1)</u></p> <p>The fire alarm system is inadequately maintained</p> <p><u>Article 17 (1)</u></p> <p>The emergency lighting is inadequately maintained</p>
Reference No:	EN.NA.604
Date of compliance of notice:	03.01.19

Date on which notice served:	18.12.17
Name of Organisation:	Specialised Aerosols Co Ltd, Carr Green Lane, Mapplewell, Barnsley, S75 6DY
Type of notice served:	Enforcement
Details:	<p>Article 9 (1)</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 8 (1) (a)</p> <p>To take such general fire precautions as will ensure the safety of employees.</p> <p>Article 10</p> <p>Preventative and protective measures have not been implemented in accordance with the principles of prevention as specified in Part 3 of Schedule 1 of the Regulatory Reform (Fire Safety) Order 2005</p> <p>Article 11 (1) & (2)</p> <p>A fire safety policy document has not been prepared</p> <p>Article 12 (1) & (2)</p> <p>The risks from a dangerous substance have not been eliminated and/or reduced and/or replaced so far as is reasonably practicable</p> <p>Article 12 (4) (a)</p> <p>Arrangements for the safe handling and/or storage and/or transport of dangerous substances and/or waste containing dangerous substances is inadequate</p> <p>Article 13 (1) (a) & 13 (2)</p> <p>The fire detection system is inadequate</p> <p>Article 14 (1)</p> <p>The escape routes were obstructed</p> <p>Article 14 (2) (f)</p> <p>Fire exits and doors on escape routes could not be easily and immediately opened from the inside</p> <p>Article 14 (2) (h)</p> <p>The escape routes did not have adequate emergency lighting in case of</p>

	<p>failure of normal lighting circuits</p> <p>Article 15 (1) (a)</p> <p>Insufficient evacuation procedures and/or evacuation drills to be followed in the event of serious and imminent danger are in place</p> <p>Article 16 (1) (a) (i) & (ii)</p> <p>Inadequate information is available on emergency arrangements to safeguard persons from dangerous substances involved in an accident, incident or emergency</p> <p>Article 17 (1)</p> <p>The emergency lighting is inadequately maintained</p> <p>Article 21 (2) (b)</p> <p>Safety training to employees is not repeated periodically</p>
Reference No:	EN.NA.556
Date of compliance of notice:	05.03.18

Date on which notice served:	20.11.17
Name of Organisation:	Regent House, 11 Regent Street, Barnsley, S70 2EG
Type of notice served:	Enforcement
Details:	<p>Article 8 (1) (b)</p> <p>To take such general fire precautions as will ensure the safety of persons who are not his employees</p> <p>Article 9 (1)</p> <p>A Fire Safety Risk Assessment has not been carried out.</p> <p>Article 11 (1) & (2)</p> <p>A fire safety policy document has not been prepared</p> <p>Article 13 (1) (a) & 13 (2)</p> <p>The fire warning system is inadequate</p>

	<p>Article 14 (2) (b)</p> <p>The escape routes and exits could not be used as quickly and as safely as possible</p> <p>Article 17 (1)</p> <p>The structural fire precautions are inadequately maintained</p> <p>The fire alarm system is inadequately maintained</p> <p>The emergency lighting is inadequately maintained</p>
Reference No:	EN.NA.549
Date of compliance of notice:	05.02.18

Date on which notice served:	02.08.17
Name of Organisation:	Freaqz, 9 Peel Parade, Barnsley, S70 2RN.
Type of notice served:	Prohibition
Details:	<p>Article 13</p> <p>A suitable fire alarm system conforming to British Standard 5839: Part 1: 2013 or an equivalent standard, should be provided throughout the premises.</p> <p>The fire detection and warning system should be subject to a suitable system of maintenance, and must be maintained in an efficient state, and in efficient working order and in good repair.</p>
Reference No:	PN.NA.532
Date of compliance of notice:	07.08.17