



**South Yorkshire  
FIRE & RESCUE**

**Time of Call:** 01/01/2020 09:52:45  
**Type:** Primary Fire  
**Initial Incident Type:** FIRE DOMESTIC BUILDING  
**Actual Address:**

## Incident Identification

What was the time and date of Call?	01/01/2020 09:52:45
What was the origin of this call?	Person (mobile)
What was the incident type when the call was received by the control room?	Fire - Building
Time/date of stop message?	01/01/2020 11:45:00
Time/date incident closed	01/01/2020 11:46:08

## Incident Details On Attendance

Please indicate if this is a Fire, Special Service, False Alarm or Other incident	Fire
What type of property was involved?	Building > Dwelling > House - single occupancy
Please indicate if there were persons rescued, extricated, injured or killed in the incident	No
Please indicate if there were persons evacuated in the incident	Yes
How many pumping appliances attended the incident before mobilisation stopped?	3

## On Attendance - Additional Info

Did the fire have multiple seats?	No
How long was it between ignition and discovery?	Over 2 hours
How long was it between discovery and first call?	Immediately
How was the fire discovered?	Person
Do fire safety regulations apply?	No
Was there any alarm system present?	Yes <a href="#">Go to page 3 for Alarm Type(s)</a>
Was there anyone in the building at the time of the fire?	Yes
Is the building normally occupied?	Yes - occupied
Cause / Motive	Accidental
Were there any hazardous materials involved?	No

## On Attendance - Action

What was the main action taken by the general public prior to arrival?	Smothering
--	------------

<b>What was the main action taken by FRS Personnel?</b>	Portable extinguishers - Dry powder (DP)
<b>Were any manual systems used?</b>	No
<b>Were there any active safety system present?</b>	No

## On Attendance - Damage

---

<b>What was the cause of the fire?</b>	Faulty fuel supply - electricity
<b>Caused by?</b>	Not known
<b>What was the source of ignition?</b>	Electricity supply - Wiring, cabling, plugs
<b>What powered the ignition?</b>	Electric
<b>What item/material was damaged first?</b>	Foam, rubber, plastic Plastic raw material only
<b>What was the item, if any, mainly responsible for the spread of the fire?</b>	Foam, rubber, plastic - Plastic - raw material only
<b>What type of room/compartiment did the fire start in (location of origin)?</b>	Other
<b>Was there heat and/or smoke damage only (no flame)?</b>	No
<b>What was the extent of flame &amp; heat damage on arrival?</b>	Limited to floor of origin (not whole building)
<b>If any adjacent properties were affected at the time you arrived, how far away were they (m)?</b>	No other property affected
<b>What was the extent of flame &amp; heat damage (at stop)?</b>	Limited to floor of origin (not whole building)
<b>If any adjacent properties were affected at stop, how far away were they (m)?</b>	No other property affected
<b>What is the extent of the area that is fire damaged (sq/m at stop)?</b>	Up to 5
<b>What was the extent of the total area damaged? (sq/m at stop, including fire, water, heat and smoke damage)?</b>	Up to 5
<b>What is the approximate size of the floor of the fire's origin (sq/m)?</b>	Up to 5

---

## Type of Alarms

---

<b>Alarm System Type</b>	<b>Alarm System Location</b>	<b>Alarm System operated?</b>
Smoke alarm - 1 year battery	On same floor as fire	No

**It is emphasised that the detail in this report is the view of the Officer in Charge of the incident at the time of completion.  
The information is extracted from a dynamic system and is correct at the date and time of issue.**